Remington Arms Co., Inc. Product Service Legal Case #:7510

Case Information

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Obsolete Lit 3/20/2012 3/21/2012 3/21/2012 2/11/2012 262443

Customer Information

Type **Business** First Name Last Name Street City State Zip Contact Age 144 Patricia Dr. Beaver Falls PA 15010 H 724-417-1940 Incident Jarrett Wagner

Incident Information

Claims Codes **Medical Treatment Medical Status** Repair Est.

ΡI

PD Cause: 4006 Altered Adjustments or Components Concern:1007 Fired on Safe Release

Unknown

S C

FSR

SR# 14342 - Reason for Return: Trigger. Service Request Section: Going from safe to fire the gun fired. df

Firearm Information

SKU Mfg. Type Model/Ga. Serial Bbl. DOM Remington CF/BA 700/223 REM 85351 G6681222 WB 8/16/2007 5:50:21 PM **Date Purchased** Where Purchased Accessories **Original Owner**

DICK S SPORTING GOODS

U

CONCERN: FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Cash Reim. Date Cash Date Settlement Release of Claims Release Date Reimbursement Settlement APV APV

Per Ilion - Quote to гераіг

Repair/Replacement Cost Repair/Replacement Date

3/26/12: Per Ilion - Trigger pull set below min. specs. Trigger not returning properly. Can offer to replace TA, check over & test fire @ 1/2 normal cost. df 4/3/12: Customer paid quote. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		3/21/2012
	Product Type]	RF
	Action Type]	A
	Assigned To]	T.NAGLE
Cause	4006	Altered Adjustments or Components	
Dariei	Description		26" 223 REM VTR
	Date Code]	WB
	Bore Plugged	False	
	Bulged	False	
	Fired	False]
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=7510&Type=Case

4/3/2012

Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning]
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	Select	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select]
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False]
Safety	Description		XMP SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS]
Sear	Lift	Select	.010
	Notch	Slightly Worn; Functioning]
		Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	TRIG NOT RETURNING PROPERLY WILL FOLLOW DOWN
	Pull	Select	2#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	X-Mark Pro	7

7510

Zb (1 WB8/07 Z# ,010

March 14, 2012

Dear Remington Technician:

I wanted to give you a brief explanation of the issue with this firearm. On the morning of February 11, 2012, I was coyote hunting and had a coyote coming in. When I flipped the safety from safe to fire, the firearm discharged. I immediately unloaded the firearm to see if I could get it to do it again, and it did...multiple times. So I stopped hunting and took it home. It was approximately 15 degrees Fahrenheit that morning. After the rifle warmed up to room temperature (approximately 70 degrees Fahrenheit), it would no longer fire when moving from safe to fire. So I took the stock off, sprayed some break-free in the trigger mechanism, put the stock back on and set it outside for several hours. I had the same issue in the cold again...would discharge when moving from safe to fire. I then called to send the rifle in to Remington. At room temperature, I notice a large variance in the trigger pull...sometimes ounces all the way up to just under four pounds. I prefer a consistent three pound trigger pull. I hope this can be achieved with this quality of rifle.

Thank you very much.

Jarrett Wagner

144 Patricia Drive

Beaver Falls, PA 15010

724-417-1940




Trig. pull set below minispers.

Trig. Not returning properly.

CAN ofher to replace TPA chick

Onen + Nest At 1/2 Normaliest



BY:____

COLLING LIGHTON

PU DOX 700

Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700 F:336-548-7801 www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCI YOUR RETURN.

Service Request Numberial Number / Description

SR00014342

G6681222

Model 700 RIFLE Caliber: 223

Customer: JARRETT WAGNER

144 PATRICIA DR BEAVER FALLS, PA 15010 US

Email: jwagnerz û vahoo.com

BEAVER FALLS, PA 13010 US

Date of Request03 02 2012

Date Printed33.02.2012

Destination: Arms Services

Anns Services 14 Hoefler Ave Ilion, NY 13357 US

Email.

Your request for service on the item(s) will be evaluated by our repairment to determine if it is covered under our warranty policy. If it is your firearm will be repreturned. If not, you will be contacted with an estimate before work is performed.

Reason For Return M994 - TRIGGER

NIPPH - IRIUGER

Service Request Section

Went going from safety to fire the gun fired.

Parts And Service Details

Material

Type

Description

Qty Warranty Needed Price Disc Amount

Sub Total: Est Sales Tax: .00

Grand Total:

\$.00

[724] 770-9081

003 52615 11/06/1 LAYAWAY 328 SALE 0792 05:15 PM ACCOUNT # : 328001855 JARRETT WACHER 354 FRIENDSHIP RD BLOVER FALLS PA 15010 View - 17-1940 *700 SPG HARMING ALLS W SHART 479,98 047700653512 CURRENT: ...99 SALE NEW \$479.98 41.17 CUSTOMER 10: 294608539655 479.97 SUBTOTAL 1 ITEMS TOTAL TAX 28.50 TOTAL \$500 %. - X X X X 7 ._____ SCHEDULI INTHENT AMCE NO DATE 11/21/07 101 PAYMENT 1 PAYMENT 2 12/06/07 12/21/07 101 PAYMENT 3 101.77 PAYMENT 4 01/05/08 BALANCE LUL 407.02 549,93 REGULAR PROJUL YOU SAVED *\$1*0.0i أيار الأخراج أأنان المهاريس والمجابرتين 自由家 YOU FOR SHOPPING AT DICK'S and www.look-Sportlandands.com . aCard Rows — Account at transfer The Responding to the unline dustomer burvey : tingGoods.com/feedback to our next purchase of \$ or must be completed within

19 hours of stone VI 11



