Remington Arms Co., Inc. Product Service Legal Case #:7473

Case Information

RE# Date Opened 261242 3/8/2012

Date Opened(PS) 3/9/2012

Date Closed

Incident Date

Salem

Pre Lit Lit

Obsolete

Customer Information

Type

Business First Name

Last Name Wholesale Sport

Street 1260 Lancaster Dr SE

3/9/2012

City State Zip Age Contact

Wholesale Sports Reporter Incident Information

Claims

Codes

OR Repair Est. Medical Treatment W 503-589-0800

Medical Status

ΡI PD

Cause: 4038 Could Not Duplicate Concern

S Fired on safety release Concern:1007 Fired on Safe Release

Unknown

97317

3/29/12 Per note with rifle, gun fires when safety is moved from safe to fire.cm

Firearm Information

Mfg.

Type CF/BA Model/Ga.

SKU 84371 Serial Bbl.

DOM

G6934955 BE 1/25/2010 11:29:41 AM

Remington **Date Purchased**

Where Purchased

700/308 WIN Accessories

Original Owner

WHOLESALE SPORTS/SPORTSMA TWO PIECE BASE

CONCERN: FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Settlement

Release of Claims

Release Date

Reimbursement

Reim. Cash

Settlement

Cash

Date Date APV

Per Ilion, to restore confidence in the rifle will replace, check over and test at no charge

Repair/Replacement Repair/Replacement

Cost

Date

50.63

3/29/2012

3/29/12 Per Ilion, could not duplicate concern. As a goodwill gesture to restore confidence in the rifle will replace, check over and test at no charge.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		3/9/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 308 VTR BRAKE
	Date Code		BE
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=7473&Type=Case

3/29/2012

	Muzzle/Crown Condition	Slightly Worn; Functioning Slightly Worn; Functioning	<u> </u>
	Firing Pin		
Bolt	Shroud	Slightly Worn; Functioning	<u> </u>
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		XMP SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.012
Sear	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Functioning	
.	Pull	Select	3#
Trigger	Altered	False	
	Sub-Assembly	X-Mark Pro	
Non-Remington Components	Description		TWO PIECE BASE

⊼
ဖွ
ત
PS

: tagl 000! <u>() 100</u>	
City: <u>ILION</u> State: M Zip: 13357	
RA/RMA Number:	
Insured Value: \$\$ <i>&Oq</i>	0,172
Store Information: (Use Store Address Stamp Here) Wholesale Sports #109 1260 Lancaster Dr SE	1412
Wholesale Sports #109 1260 Lancaster Dr. SE	
Salem, Oregon 97317	
Phone:503-589-0800 Fax:503-589-0802	
Store Phone Number: 503-589-0800	
Firearm Information:	•
11. 12. 12. 12. 12. 12. 12. 12. 12. 12.	
Manufacturer / Importer: Remington 700	
Common Model: VTR Caliber/Gauge: 306	-
	•
Serial Number: GG34955 Type:	•
Li 100 0077 (i.e. Store number (XX) followed by book	•
Log Number: 4-109-002-21 (i.e. Store number (XX) followed by book (26) and log # - XX26-XXXX)	,
Shipped with the following:Magazine(s) Scope Rings Bolt	
Chokes Other Scepe bases	
	• .
Problem: (Be as specific as possible)	
	•
Gun fires when safety is moved from	•
· · · · · · · · · · · · · · · · · · ·	
"Safe" to "fire"	,
•	
,	
· · · · · · · · · · · · · · · · · · ·	z [v]
Customer Name: Lev. Vandermolen	A Q
	[(v)]
Customer Phone: KAZ FOT-ALL	A R-n

Farm to repair facility. Yellow Copy: To be retained and filed by the Hunting Department by year.

n is originally dropped off to store for repair.

.,

" HOLFIED WIL

2012

Rev. 7/09

contideret duplicate concern A Good-Will Gusture to restor contidence in rifle will replace checkoneratest At M/c

G6934955 Model:







