Remington Arms Co., Inc. Product Service Legal Case #:8245

Case Information

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete 295116 1/4/2013 11/29/2012 11/29/2012

Customer Information

Last Name Zip Contact Business First Name Street City State Age Type 357 30 Rd OK E osage1954@yahoo.com Incident Sid Wilson Ponca City 74604

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PI bruised thumb

PD shot through floorboard and transmission

Cause:4038 Could Not Duplicate Concern Concern:1020 Fired on Bolt Opening

U

S C

11/29/12 Per call from Wilson, his 700 SPS Tactical fired when he went to unload it. He was standing outside his pick-up and it fired through the floorboard and transmission. He has about \$3000 damage to his truck.cm

Firearm Information

 Mfg.
 Type
 Model/Ga.
 SKU
 Serial
 Bbl.
 DOM

 Remington
 CF/BA
 700/308 WIN
 84207
 G6702647
 EB
 10/26/2007 8:32:57 PM

Date Purchased Where Purchased Accessories Original Owner

JERRY S SPORT CENTER NORT

Y

CONCERN: FBC

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Reim. Date Cash Date
Settlement APV APV

Repair/Replacement Cost Repair/Replacement Date

11/29/12 Emailing ARS.cm 1/10/13 Emailed S. Earl to ship to D. Watkins for inspection. Called Wilson for additional info on the incident. He said the safety was on, and he touched the safety to move to fire and just the touch caused it to fire. It had not moved to the fire position. He had not pulled the trigger prior to that while the safety was on.cm 1/24 The firearm was returned to Ilion since the address they listed was wrong. I gave them the correct address for E-town and asked them to ship it. On 1/28 it still had not shipped so I asked that they ship it one day air.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
i l	Exam Date		1/7/2013
	Product Type		RF
	Action Type		A
	Assigned To		J.BALIO
Cause	4038	Could Not Duplicate Concern	THE SEAR SPRING IS NOT POSITIONED CORRECTLY UNDER THE SEAR. SEE PHOTO
	Description		20" 308 HB
	Date Code		EB
	Bore Plugged	False	
į	Bulged	False	
	Fired	False	
	Fired while		-

	Obstructed		
	Muzzlc/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	DIRTY
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
0-6-	Description		XMP SAFETY
Safety	Function	Like new; Functioning	
	Lift	Select	.011
Sear	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Wom; Functioning	
Trigger	Pull	Select	4.5#
	Altered	False	
	Sub-Assembly	X-Mark Pro	

Service Request

Remington Service PO Box 700

Madison, NC 27025-0700

ATTN: Prod Serv #8245

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service.PLEASE RETAIN THIS COPY FOR YOUR RECORDS.

	Serial Number / Description			Request:	11/30/2012
SR00036958	G6702647		Date	Printed:	11/30/2012
Customer:	Model 700 RIFLE Caliber: 308	Destination:			
SID WILSON 357 30 RD		Arms Services 14 Hoefler Ave			
PONCA CITY, OK 74	4604 US	Ilion, NY 13357	US		
Email: osage1954@yah		Email:			
Vour request for service on the	e item(s) will be evaluated by our repairman to determine if it	is covered under our warranty nol	icy If it is	vour firearm	will be renaired and
returned. If not, you will be co	ontacted with an estimate before work is performed.				
Reason For Return M123 - FORWARD TO	PRODUCT SERVICE FOR INSPECTION				
Service Request Section	and the second s				
Prod Serv #8245					
Parts And Service Details Material Type	Description	Qty Warranty Needed		Price	Disc Amount
		Needed			
THIS IS NOT AN INVOICE. The being sent based on the conver	This is a pre-estimate to repair, recondition, or replace the itersation with our representative.	m(s)		b Total: t Sales Tax:	.00
			Gr	and Total	\$.00

Please send your firearm back via a traceable method of shipping to the address below.

This Service Request number is only valid for this return.

Please follow these guidelines:

- Include a copy of your proof of purchase to assist in the evaluation of your repair
- Record your serial number for future reference
- Remove <u>any</u> accessories (sling, scope, scope mounts, case, etc.) unless these items are needed to assist in the evaluation.
- Properly package your <u>unloaded</u> firearm. Do not ship in your hard case (note: Original boxes are not returned with repair)
- Do not send live/loaded or spent ammunition with your firearm.
- Please package the ammunition in a secure carton or box.
- The package should be stuffed to prevent movement.
- Include service request number.
- Shipment of live ammo must be via U.P.S. only.
- Please advise your local U.P.S. mailing center of the contents so that a special Other Regulated Materials-Domestic (ORM-D) label can be applied.

Please let us know of any address change requests by email or phone. Our returns process will take approximately 2-3 weeks to complete and a confirmation email will be sent once we have shipped your firearm.

Should you have any further questions or concerns please don't hesitate to contact us via email (<u>info@remington.com</u> << <u>mailto:info@remington.com</u>>>) or by phone at 800-243-9700, M-F 9am - 5pm, EST. We look forward to helping you resolve this issue!

Mailing Label:	
(cut here)	

Arms Services SR# SR00036958 14 Hoefler Ave Ilion, NY 13357 US

Email:

Attn: Prod Serv #8245



ARS LABEL REQUEST FORM

Service Request #

SR00036958

QUANTITY:	1	WEIGHT PER PACKAGE: 10 LBS
REQUESTED BY:	mitchellcs	email address:
Business:		Remington Service PO Box 700 Madison, NC 27025-0700 www.Remington.com
		LABEL INFORMATION
MAIL LABE	L TO:	SID WILSON 357 30 RD PONCA CITY, OK 74604 US SR00036958

Email: osage1954@yahoo.com

ILN

Arms Services



4XX596 SVC GNDCOM TRACKING# 1Z4 REF 1:SR00036 REF 2:	XX59		2012 ACT UT 55594599	10 A	CURR LBS	USD	1	OF	1
HANDLING CHAR	GE Ø	aa							

SINGLE-PIECE PUB RATE CHRGS: SVC T/P USD DV 0.00 COD 0.00 RS 1.00 DC 0.00 DGD 0.00 SD 0.00 AH 0.00 PR 0.00 SP 0.00 TOT PUB CHG 11.38 PUB+HANDLING 11.38

ATTN: Prod Serv #8245

RETURN ITEM TO:

DATE:

11/30/2012

ARS LABEL REQUEST FORM

DATE:	12/03/2012		Service Request #	SR00036938
QUANTITY:	1		WEIGHT PER PACKAGE:	10 LBS
REQUESTED BY:	mitchelles		email address:	
Business:				
Dusiliess.		Remington Servi PO Box 700		
		Madison, NC 27 www.Remington		
		LABEL IN	IFORMATION	
MAIL LABEL	. TO:	SID WILSON		
		357 30 RD PONCA CITY, (OK 74604 US	
		SR00036958	10.1	
		Email: osage1954	(@yanoo.com	
RETURN ITE	EM TO:	ILN		
		Arms Services		



DEC 3, 2017

AXX596 DEC 3, 2017

SVC GNDCOM ACT WT 10.0 LBS

TRACKING# 1Z4XX5C ACT WT 10.0 LBS

TRACKING# 1.SR0003F'_958

REF 1:SR0003F'_958

REF 2:

ATTN: Prod Serv #8245

HANDLING CHARGE 0.00

SINGLE-PIECE PUB RATE CHRGS: SVC T/P USD

AV 0.00 COD 0.00 RS 1.00

DC 0.00 DGD 0.00 SD 0.00

AH 0.00 PR 0.00 SP 0.00

TOT PUB CHG 11.38 PUB+HANDLING 11.38





