

Remington Arms Co., Inc.
Product Service
Legal Case #:8370

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
292979	12/14/2012	12/17/2012	12/17/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Ryan	Winner	1507 23rd St	Cody	WY	82414		E winner@codylabs.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4006	Altered Adjustments or Components		Unknown
S	Fires when on safe	Concern:1032 Safety not working properly		
C				
12/28/12 Per note on SR, fires when on safe.cm				

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/243 WIN	84170	G6639605	BB	1/24/2007 6:44:08 AM
Date Purchased	Where Purchased	Accessories	Original Owner			
	ACUSPORT (OH) CORPORATION		U			
CONCERN: FSR						

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean and test at 1/2 normal cost						

Repair/Replacement Cost	Repair/Replacement Date

12/28/12 Per Ilion, trigger assm set screws altered and has a dried and sticky lube residue. Bore was plugged with a bullet and action had a log of unburned powder. Was unable to close bolt until cleaned. Replace TPA, clean and test at 1/2 normal cost.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		12/17/2012
	Product Type		RF
	Action Type		A
	Assigned To		J.BALIO
		Altered Adjustments or	

Cause	4006	Components	
Barrel	Description		24" 243 WIN
	Date Code		BB
	Bore Plugged	True	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	SOME BRASS WASH
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Not Functioning	BINDS
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	BULLET REMOVED FROM BORE ACTION HAD EXCESSIVE UNBURNED POWDER AND STICKY LUBE RESIDUE
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		XMP SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	.010
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	TRIG NOT RETURNING WILL FOLLOW DOWN
	Pull	---Select---	2#
	Altered	True	SET SCREWS ALTERED

	Sub-Assembly	X-Mark Pro
--	--------------	------------

PO Box 500
Madison, NC 27025-0700

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

Parts and Repairs: P-800-243-9700 F-336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. PLEASE RETAIN THIS COPY FOR YOUR RECORDS.

24"
BB/07
24
010

Service Request Number: SR00036330
Serial Number / Description: G6639605
Model: 8370
Date of Request: 11/27/2012
Date Printed: 11/29/2012
Customer: RYAN WINNER
1507 23RD ST
CODY, WY 82414 US
Destination: Arms Services
14 Hoefler Ave
Ilion, NY 13357 US

Email: winner@codylabs.com

Email:

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return
M568 - SAFETY BROKEN

Service Request Section
FIRES WHEN ON SAFE

Parts And Service Details
Material Type Description Qty Needed Warranty Price Disc Amount

Serial Number:

G6639605

Model: 700



RE00292979

T.A. set screws altered. Has a dried, sticky lube residue. Barrel was plugged w/ Bullet + act. had a lot of unburned powder was unable to close bolt until cleaned. Rep. TPA, clean + rust at 1/2 charge

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the

RECEIVED
DEC 19 2012

Sub Total: .00
Est Sales Tax: .00
Grand Total: \$.00

BY:.....





