Remington Arms Co., Inc. Product Service Legal Case #:7604

Case Information RE# Date Opened Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete 265324 4/20/2012 4/23/2012 4/23/2012 Customer Information State Zip Age Contact Type Business First Name Last Name Street City 22292 Williams Rd SE Incident Arlon Eriksson Cass Lake MN 56633 E eriksson@paulbunyan.net Incident Information Repair Est. Medical Treatment Medical Status Claims Codes PΙ PD Cause: 4038 Could Not Duplicate Concern Unknown Concern:1007 Fired on Safe Release S Fires when removing safety 5/9/12 Per note on SR, gun fires when removing safety. Customer wrote a note to replace the pistol grip butt plate.cm Firearm Information Mfg. Type Model/Ga. SKU Serial Bbl. DOM Remington CF/BA 7/243 WIN 24782 7600225 XC 12/1/1982 **Date Purchased** Where Purchased Accessories **Original Owner** FABER BROS CHICAGO IL SCOPE BASE U CONCERN:FSR Ammunition Information - None Defined Other Products Information - None Defined Settlement Remington/7/CF/BA Cash Reim. Date Cash Date Settlement Release of Claims Release Date Reimbursement APV Settlement APV Can offer to replace TPA, clean,

test at 1/2 normal cost

Repair/Replacement Repair/Replacement Cost Date

5/9/12 Per Ilion, could not duplicate concern. Trigger assm very dirty. Can offer to replace TPA, clean, test at 1/2 normal cost. Unable to replace stock. Can replace with a used in good condition.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
Examination	Exam Date	]	4/23/2012
	Product Type	]	RF
	Action Type		A
	Assigned To	]	T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		18.5" 243 WIN
	Date Code	]	XC
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	]
	Firing Pin	Slightly Worn; Functioning	]

http://cns03an13:200/nsaann/PrintDisplay asnx?ID=7604&Tyne=Case

5/9/2012

fı .	1		_
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	7
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Worn; Functioning	GRIP CAP BROKEN,O/S FLOOR PLATE
	Fore End Condition	Select	
	Condition	Slightly Worn; Functioning	7
Receiver	Bulged	False	
	Description		M/7 SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.013
Sear	Notch	Slightly Worn; Functioning	
	T	Test Fired	False
Feeding Test	= Tests	False	
	Condition	Slightly Worn; Functioning	
T:	Pull	Select	3.5#
Trigger	Altered	True	PULL SCREW ALTERED
	Sub-Assembly	Other Remington	
Non-Remington Components Description			SCOPE BASE

## Madison, NC 27025-0700.

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

Service Request Number SR00017607

Serial Number / Description

7600225

Model SEVEN RIFLE Caliber: 243

Date of Request: Date Printed:

04/17/2012 04/17/2012

Customer: ARLON ERIKSSON 22292 WILLIAMS RD. SE CASS LAKE, MN 56633 US Destination: Arms Services 14 Hoefler Ave Ilion, NY 13357 US

Email: eriksson@paulbunyan.net

-Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return

M510 - CHECK TRIGGER PULL

Service Request Section

gun fires when removing safety!

also, please replace the pistul grip but plate.

Parts And Service Details
Material Type Description

Disc Amount

**讃7600225** 



APR 2 6 2012

could not dap, concern. T.A. very dinty CAN offen 96 Rep. TRA, CLOAN + TRST A+1/2

URAble to Kp. StK. CAN Nep. W/Ausel IN good coid.

Sub Total:

.00

Est Sales Tax: Grand Total:

\$.00

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the





