

Remington Arms Co., Inc.
Product Service
Legal Case #:8343

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
292422	12/11/2012	12/12/2012	12/12/2012				X

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Danny	Calhoun	2105 Austin St	San Angelo	TX	76903		E DDC.Ranch@gmail.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4015	Improper Maintenance		
S	Gun went off without pulling trigger	Concern:1025	Unexplained Discharge - No Mention of Safety Position	Unknown
C				
12/28/12 Per note on SR, gun went off without pulling the trigger.cm				

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	600/243 WIN	n/a	80419	PP	6/1/1967
Date Purchased	Where Purchased	Accessories	Original Owner			
			U			

CONCERN: WENT OFF NOT PULLING TRIGGER

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/600/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean and test at no charge under recall						
	Repair/Replacement Cost	Repair/Replacement Date				
	43.81	12/28/2012				

12/28/12 Per Ilion, trigger assm dirty and sticky, parts bind and work sluggish. Replace TPA, clean and test at no charge under recall.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		12/12/2012
	Product Type		RF
	Action Type		A
	Assigned To		J.BALIO
Cause	4015	Improper Maintenance	
Barrel	Description		18.5" 243 WIN
	Date Code		PP
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	SLUGGISH
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	.008
	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	DIRTY STICKY PARTS BIND WORK SLIGGISH WILL FOLLOW DOWN
	Pull	---Select---	4.5#
	Altered	False	
	Sub-Assembly	Other Remington	

Parts and Repairs: P:800-243-9700 F:336-548-7801
www.Remington.com
This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. **ENCLOSE THIS DOCUMENT WITH YOUR RETURN.**

Service Request Number: 00036619
Serial Number / Description: 8343
Date of Request: 11-29-2012
Date Printed: 11-29-2012
Customer: DANNY CALHOUN
2105 AUSTIN ST.
SAN ANGELO, TX 76903 US
Destination: Arms Services
14 Hoefler Ave
Elion, NY 13357 US

Email: DDC.RANCH@GMAIL.COM
Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return
240 - BOLT LOCK SAFETY MODIFICATION
295 - EVALUATE AND REPAIR SAFETY INSP.

Service Request Section
GUN WENT OFF WITHOUT PULLING TRIGGER.

Parts And Service Details

Qty Needed	Warranty	Price	Disc	Amount
------------	----------	-------	------	--------

Serial Number: 80419
Model: 600 MOHAWK

RE00292422

RECEIVED
DEC 13 2012
BY:.....

T.A. dirty & sticky
PARTS BIND + work
sluggish. Rep T.A.
clean & test AT N/C
und. recall
#230145

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the

Sub Total: .00
Est Sales Tax: .00
Grand Total: \$.00