

Remington Arms Co., Inc.

Product Service

Legal Case #:8199

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
289966	11/20/2012	11/27/2012	11/27/2012				X

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Collier Wood Shop	Collier	Wood Sh	107 N. Jefferson	Magnolia	AR	71753		E.collierwoodshop@yahoo.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4006	Altered Adjustments or Components		
S	Had an accidental discharge	Concern:1025	Unexplained Discharge - No Mention of Safety Position	Unknown
C				
12/11/12 Per note on SR, the owner had an accidental discharge.cm				

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	600/6MM REM	r/a	6874523	PZ	6/20/1975
Date Purchased	Where Purchased	Accessories	Original Owner			
	SPORTS SOUTH LAKE CHARLES LA	AFT MKT STK	U			

CONCERN:ACCIDENTAL DISCHARGES

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean, test at no charge under recall						
	Repair/Replacement Cost	Repair/Replacement Date				
	43.81	12/11/2012				

12/11/12 Per Ilion, trigger assm set screws altered. Replace TPA, clean, test at no charge under recall.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		11/27/2012
	Product Type		RF
	Action Type		A
	Assigned To		J.BALIO
Cause	4006	Altered Adjustments or Components	
Barrel	Description		18.5" 6MM REM
	Date Code		PZ
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	---Select---	AFT MKT
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.015
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	TRIG NOT RETURNING
	Pull	---Select---	2.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	Other Remington	
Non-Remington Components	Description		AFT MKT STK

2.5#

P26/7
015

Slideshow

Return to Yahoo! Mail

8199

Collier Wood Shop

Service Request

Remington Service
PO Box 766



Madsen, NC 27425-0766

www.Remington.com

Part and Repair: P-800-243-9700 F-326-548-7801

This document is a summary of your request for service. Please review this document for accuracy and to insure the service you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

Service Request Number SR003-170	Serial Number / Description 6874522 600 MOHAWK Cuts Fire	Date of Request Date: 11/17/2012 Printed: 11/17/2012
Customer: COLLIER WOOD SHOP 10 N. JEFFERSON MAGNOLIA, AR 71753 US Email: collierwoodshop@yahoo.com	Destination: Arms Services 14 Hooper Ave Darien, NY 13620 US Email:	
Your request for service on this machine will be evaluated by our engineers to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.		
Reason For Return MIS - REPLACE TRIGGER ASSEMBLY UNDER RECALL		
Service Request Section Mishandled for recall has had accidental discharges.		
Part And Service Details	Description	Qty. Needed
Material	Type	Warranty
		Price
		Disc Amount
THIS IS NOT AN QUOTE. This is a pre-estimate to repair, recreation, or replace the		
Sub Total:		.00
Exc. Sales Tax:		.00
Grand Total:		\$.00

RECEIVED
NOV 29 2012

BY:.....

Serial Number:

6874523

Model: 600 MOHAWK



RE00289966

T. A. set screws altered
up TPA, clean & test ATN/c
under recall.

#230145