

Remington Arms Co., Inc.
Product Service
Legal Case #:8170

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
289051	11/15/2012	11/16/2012	11/16/2012				X

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Larry	Lavan	337 Cougar Lane	Leeper	PA	16233		H 814-744-7532

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern		Unknown	
S FSR	Concern:1007 Fired on Safe Release			
C				

SR# 33693 - Customer states the gun fires when the safety is pushed off. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	600/243 WIN	n/a	6744774	OY	7/1/1974
Date Purchased	Where Purchased	Accessories	Original Owner			
	JERRYS SPORT OLYPHANT PA	SCOPE BASE	U			

CONCERN: FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/600/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Replace TA under recall @ n/c						

Repair/Replacement Cost	Repair/Replacement Date
\$44	

11/21/12: Per Ilion - Min. sear lift. Replace TA, clean & test fire under recall @ n/c. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		11/16/2012
	Product Type		RF
	Action Type		A
	Assigned To		J.BALIO
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		18.5" 243 WIN
	Date Code		OY
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	

Bolt	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Like new; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.002
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	MIN SEAR LIFT
	Pull	---Select---	3#
	Altered	False	
	Sub-Assembly	Other Remington	
Non-Remington Components	Description		SCOPE BASE

Service Request

Remington Service

PO Box 700

Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. **ENCLOSE THIS DOCUMENT WITH YOUR RETURN.**

Service Request Number SR00033693	Serial Number / Description 6744774 Model 600 MOHAWK Center Fire	<u>8170</u>	Date of Request: 11/01/2012 Date Printed: 11/01/2012
Customer: LARRY LAVAN 337 COUGAR LANE LEEPER, PA 16233 US	Destination: Arms Services 14 Hoefler Ave Ilion, NY 13357 US	Email:	

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return
M240 - BOLT LOCK SAFETY MODIFICATION

Service Request Section
Customer states the gun fires when the safety is pushed off.

Material	Type	Description	Qty Needed	Warranty	Price	Disc	Amount
----------	------	-------------	------------	----------	-------	------	--------

Gentlemen:

THIS RIFLE HAS A VERY GOOD TRIGGER.
PLEASE DO NOT CHANGE IT.

RECEIVED
NOV 21 2012

REGARDS

Jerry J. B.
MIN. SEAR LIFT, Replace TPA,
CLEAN + TEST fire under
reach A + M/C #230145

Serial Number: 6744774
Model: 600 MOHAWK
BY:



RE00289051

1 item(s)

FSR

Sub Total:	.00
Est Sales Tax:	.00
Grand Total:	\$.00