

Remington Arms Co., Inc.
Product Service
Legal Case #:7416

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
258918	2/16/2012	2/20/2012	2/20/2012				X

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter		Kirk	Peterson	602 Cherry Plum Ct.	Sandy	UT	84070		H n/a

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4054 As received Follows Down		Unknown	
S FSR	Concern:1007 Fired on Safe Release			
C				

Customer sent rifle in. No paperwork - note on repair said "Customer stated the rifle will fire when moving the safety or bolt." df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	600/308 WIN	n/a	75862	PN	6/1/1966
Date Purchased	Where Purchased	Accessories	Original Owner			
			U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Repair under recall @ n/c						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$111					

2/27/12: Per Ilion - Check over, replace TA, clean & test fire under recall @ n/c. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B. TRAVIS
	Exam Date		2/20/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4054	As received Follows Down	
Barrel	Description		18.5" 308 WIN
	Date Code		PN
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	

Bolt	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	—Select—	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	—Select—	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	—Select—	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/600 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	—Select—	N/A
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	WILL NOT CONNECT WITH SEAR WILL FOLLOW DOWN
	Pull	—Select—	N/A
	Altered	False	
	Sub-Assembly	Other Remington	

frmREInquiry - Repair Inquiry

Repair Number: RE00258918 Serial: 75862 Model 600 Center Fire Caliber: 308 Repairman: Charles Swanson
 Verify Repair Status: Estimating 2/17/2012 4:24:49 PM

ADDRESS INFORMATION

Customer ☒ Received from **Return To** ☐ Received from
 Name: KIRK PETERSON
 Address 1: 602 CHERRY PLUM COURT
 Address 2: PO Box:
 City: SANDY
 State: UT Zip Code: 84070 Country: US
 FFL: 01011900

Contact / Condition Problems Estimate History / Status Shipping / Billing

Problems Reported

Code	Desc
M100	SEE CUSTOMERS LETTER

Problems Found

Code	Desc
M123	FORWARD TO PRODUCT SE...

Repair Notes

states fires when moving safety

Repairman's Comments

check over the VACE TPA clamp
 test fire under load 11 05 N/C
 #230145

CSR Comments

Customer states the rifle will fire when moving the safety or bolt.

BY: _____

Refresh

Close

75862
 Model: 600



RE00258918

Monday, Feb 20 2012 11:45 AM

Monday, Feb 20 2012

3:31 AM

18.5"
 BNC/66





