

Remington Arms Co., Inc.
Product Service
Legal Case #:8332

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
292217	12/10/2012	12/11/2012	12/11/2012				X

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Danny	Quisenberry	817 N. Amherst Rd. Box 107	Earth	TX	79031		H 806-638-2162 E dmquis@fivearea.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4015	Improper Maintenance		
S FSR	Concern:1007	Fired on Safe Release	Unknown	
C				

Customer sent rifle in w/note & stated he recently purchased the gun. He said the gun fires when its taken off safety or if you close the bolt with the safety in the fire position. No report of injury or damage. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl	DOM
Remington	CF/BA	600/222 REM	n/a	40656	CM	4/1/1965
Date Purchased	Where Purchased	Accessories	Original Owner			
			N			

CONCERN: FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Repair under recall @ n/c						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$44					

12/13/12: Per Ilion - TA dirty & rusty. Trigger not returning under sear. Replace TA, clean & test under recall @ n/c. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		12/11/2012
	Product Type		RF
	Action Type		A
	Assigned To		J.BALIO
Cause	4015	Improper Maintenance	
Barrel	Description		18.5" 222 REM
	Date Code		CM
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	--Select--	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	--Select--	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	--Select--	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	--Select--	N/A
	Notch	Slightly Worn; Functioning	
	Test Fired	False	
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	TRIG NOT RETURNING UNDER SEAR WILL FOLLOW DOWN DIRTY,RUSTY
	Pull	--Select--	N/A
	Altered	False	
	Sub-Assembly	Other Remington	

I RECENTLY PURCHASED THIS GUN AND UPON
SHOOTING IT, THE GUN FIRES WHEN ITS TAKEN OFF SAFETY
OF IF YOU CLOSE THE BOLT WITH THE SAFETY IN THE "FIRE" POSITION
IT GOES OFF. PER INSTRUCTIONS OF REMINGTON ARMS I AM
SENDING IT TO YOU FOR A TRIGGER REPLACEMENT.

I ALSO HAVE A MOHAWK 600

SERIAL # 6670206 DO I NEED TO SEND IT IN TOO?

8332

Thank You

Danny Quisenberry

Box 107

817 N. Amherst Rd.

EARTH, TX

79031

dmguis@livearea.com

(806) 638-2162

Serial
Number:

40656

Model: 600



RE00292217

T. A. Dinty & Rusty
TRIG. NOT RETURNING UNDER
SEAR. REP. TPK, CLEAN & REIS
CNC. RECD AT 10/6
#230145

SHIPPED DEC 13 PAID