

Remington Arms Co., Inc.  
Product Service  
Legal Case #:7694

## Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
269496	5/29/2012	5/30/2012	5/30/2012				X

## Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Allen Arms Indoor Range	---	Allen Arms Indo	1210 Poinsette Hwy	Greenville	SC	29609		W 864-250-2007 E fnak@allenarms.net

## Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4006 Altered Adjustments or Components		Unknown	
S	Safety not working properly Concern:1032 Safety not working properly			
C				

Dealer sent rifle in. Dealer stated the safety and bolt can be manipulated in a way that will result in a discharge. df

## Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	660/243 WIN	n/a	123959	DR	9/1/1968
Date Purchased	Where Purchased	Accessories	Original Owner			
		AFT MKT STK	U			

CONCERN:BOLT AND SAFETY CAN BE MANIPULATED TO CAUSE DISCHARGE

Ammunition Information - None Defined

Other Products Information - None Defined

## Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Repair @ n/c - recall						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$44					

5/31/12: Per Ilion - Safety detent ball missing. Replace TA under recall @ n/c. df

## Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		5/30/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4006	Altered Adjustments or Components	
Barrel	Description		20" 243 WIN
	Date Code		DR
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	

Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	METAL REFINISHED
	Stock Condition	---Select---	AFT MKT
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/660 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.005
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	SAFETY DETENT BALL MISSING
	Pull	---Select---	2.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	Other Remington	
Non-Remington Components	Description		AFT MKT STK

7694

<b>Model Number:</b> 660		<b>Serial Number:</b> 123959	
<b>Name:</b> allen arms indoor range		<b>Date of Purchase:</b> 01-16-2012	
<b>Address (no PO Boxes):</b> 1210 poinsettia hwy			
<b>City:</b> greenville	<b>State:</b> sc	<b>Zip:</b> 29609	
<b>Phone</b> (Daytime): 8642502007		<b>Fax:</b> 8642710806	
<b>E-mail Address:</b> frank@allenarms.net			
<b>Please describe your problem:</b> safety and bolt can be manipulated in away that will result in a discharge safety detent ball missing by TPA under recall at N/c #230145 425 characters left			
<b>NOTE:</b> Prior to shipping your firearm, contact the Repair Center for services provided and estimated repair time.			

2011  
2.5A  
1005  
029/68

123959

Model: 660



RE00269496

LIVE OR SPENT SHELLS IN THE SAME BOX WITH THE  
 TION OF FEDERAL LAW. IF  
 ID SPENT SHELLS PLEASE  
 E PACKAGE AND INCLUDE  
 P CODE), TELEPHONE AND  
 IBER OF YOUR FIREARM.

RECEIVED

MAY 31 2012

BY: .....

- :: Record the serial number of your firearm before sending it.
- :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.)

:: Remove all accessories from your firearm to prevent loss or damage.

:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Print

Reset







