Remington Arms Co., Inc. Product Service Legal Case #:7829

Case Information

RE# Date Opened Date Opened(PS) Date Closed **Incident Date** Pre Lit Obsolete 278342 8/14/2012 8/2/2012 8/21/2012 8/1/2012 X

Customer Information

Business First Name Last Name Type Street City State Zip Age Contact Incident Charles Enochs 12220 N. Gripping Springs Rd. Columbia MO C 573-356-1774 65202

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

ΡI

PD

Cause: 4006 Altered Adjustments or Components

S FSR while dry firing

Concern: 1007 Fired on Safe Release

Unknown

8/2/12: Customer called in. He stated he bought gun used & while dry firing he had a FSR. df

Firearm Information

Mfg. Remington

Type CF/BA

Model/Ga. 660/308 WIN SKU n/a

Serial

Bbl. DOM

Date Purchased

Where Purchased

Accessories

Original Owner

110914 CR 4/1/1968

Ν

CONCERN: FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/660/CF/BA

Release Date Reimbursement

Cash Settlement APV

Reim. Date Cash Date APV

Settlement Per Ilion - Repair under

recall

Repair/Replacement Cost \$44

Release of Claims

Repair/Replacement

Date

8/3/12: Sending a box, ARS & forms from Madison office. df 8/22/12: Per llion - TA dirty & sticky. Safety detent ball missing. Replace TA, clean & test fire under recall @ n/c. df


Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		8/21/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause		Altered Adjustments or Components	
	Description		20" 308 WIN
	Date Code		CR
Barrel	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		<del></del>

	Muzzle/Crown	Slightly Worn; Functioning	1
	Condition	Slightly worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		BOLT LOCK SAFETY
	Function	Slightly Worn; Not Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	Select	.007
	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Worn; Not Functioning	DIRTY,STICKY,SAFETY DETENT BALL MISSINGWILL FOLLOW DOWN
	Pull	Select	3#
	Altered	True	SET SCRES ALTERED
	Sub-Assembly	Other Remington	· ·

7829

August 2, 2012



Charles Enochs 12220 N. Gripping Springs Rd. Columbia, MO 65202 Phone: 573-356-1774

Ref: #7829, Model 660, Serial #110914

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our facility for examination and service request.

Please include a copy of this <u>letter and service request</u> to put inside the shipping container. The letter and service request inside are important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results. I will contact you once I get the report.

I hope this action will keep you a loyal Remington customer.

Sincerely, Dell Fulcher Consumer Affairs Administrator Remington Arms Co., LLC

Phone: 1-800-243-9700 press 0 and ask for ext 8686

Fax: 336-548-7872

DECEIVED AUG 2 2 2012

110914 Model: 660 RE00278342

T.A. Linky esticky, safety detent ball missing. Rymac TPA, char stost under Recall at H/c #230148

Remington Arms Company, LLC • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

## Service Request

## Remington Service PO Box 700

Madison, NC 27025-0700

ATTN: Product Service

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

08/03/2012 Service Request Number | Serial Number | Description Date of Request: SR00025786 110914 Date 08/03/2012 Printed: Model 660 Center Fire Caliber: 308 Destination: Customer CHARLES ENOCHS Arms Services 12220 N. GRIPPING SPRINGS RD. 14 Hoefler Ave Ilion, NY 13357 US COLUMBIA, MO 65202 US Email: Email: Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed. Reason For Return M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION Service Request Section Product Service# 7829 Parts And Service Details Material Type Description Qty Warranty Price Disc Amount

Needed

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) being sent based on the conversation with our representative.

Sub Total:

.00

Est Sales Tax:

.00

Model Number:	Serial Number:					
(:6D	110914					
Name: Charles m. ENochs	Date of Purchase:					
Address (no P	O Boxes):					
	rings Rd.					
City: Columbia	State: MO Zip: 6530+					
Phone	Fax:					
(Daytime): 573-356-1774						
E-mail Address: Mrc 54fo @ aot, Com						
Please describe y	our problem:					
Please describe your problem:  RIFIC FIRED When Safety Pushed Off. Trigger						
AND Sasty do Not feel Like They are working Just						
right.	2 1112) ETE WEINTING JUST					
500 chara	cters left					
NOTE: Prior to shipping your firearm, contact the Repair Center for services provided and estimated repair time.						
provided and estima	ted repair time.					
WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.						
Record the serial number of your firearm before sending it.      Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.)      Remove all accessories from your firearm to prevent loss or damage.      Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.						
Print	Reset					

## ARS LABEL REQUEST FORM

DATE: 08/03/2012	Service Request #	SR00025786
QUANTITY: 1	WEIGHT PER PACKAGE:	10 LBS
REQUESTED BY: fulcherdm	email address:	I WILL MAIL LABEL
Business:	Remington Service PO Box 700 Madison, NC 27025-0700 www.Remington.com	
	LABEL INFORMATION	
MAIL LABEL TO:	CHARLES ENOCHS 12220 N. GRIPPING SPRINGS RD. COLUMBIA, MO 65202 US SR00025786	
	Email:	•
RETURN ITEM TO:	ILN Arms Services	
	4XX596 AUG 3, 2012 ACT WT 10.0 LBS #PK 1 SVC GNDCOM BL WT 10.0 LBS TRACKING# 1Z4XX5969065207935 ALL CURRENCY US REF 1:SR00025786 REF 2: HC 0.00 CNS 0.00 FRT: 3RD SHIPMENT PUB RATE CHARGES: SVC T/P USD SHIPMENT PUB RATE CHARGES: RS 0.50 DC 0.00 DGD 0.00	D
	AH 0.00 PR 0.00 ROD 0.00 TOT PUB CHG 10.31 PUB+HANDLING 10.31	

ATTN: Product Service

## # Pitney Bowes





Ship To:

Charles Enochs

Company:

Address 1:

12220 N. Gripping Springs Rd.

Address 2: Address 3:

City:

Columbia

State/Province:

Missouri

ZIP/Postal Code:

65202

Country:

United States

email:

Phone:

Account:

230145

Package Type:

Package

Address Type:

Residential

Deliver By:

Tue, August 7, 2012

Package ID:

8861

90

Special Instructions:

Sender Name:

Dell Marie Fulcher

email:

dell.fulcher@remington.com

Prepared By:

Dell Fulcher

Phone:

336-548-8686

Date: 08-03-12 1 1b 8.799999 oz

Acct # : 230145 Cust # : ODL0000009001 Zip/Zone: 65202 / 5 Trk # : 793865515046 Pkg ID #: 8861 Base:\$ 5.65 Spc S:\$ 0.68 Addl:\$ 0.00 Total \$ 6.33

