Remington Arms Co., Inc. Product Service Legal Case #:7089

Case Information

 RE#
 Date Opened
 Date Opened(PS)
 Date Closed
 Incident Date
 Pre Lit
 Lit
 Obsolete

 253153
 1/9/2012
 12/14/2011
 1/10/2012
 12/12/2011
 X

Customer Information

Type Business First Name Last Name Street City State Zip Contact 6608 Springdale Hunters Rd WA 99137 H 509-722-3112 Incident Russell Barnhart Hunters

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

ΡI

PD Cause:4038 Could Not Duplicate Concern
S Concern:1008 Fired on Bolt Closing

Unknown

C FBC

12/14/11: Customer called in. He stated he was using gun on 12/12/11 & had a FBC while shooting out of the window of his shop. No injury or damage reported. df

Firearm Information

Mfg. Remington

Type CF/BA Model/Ga. 710/3006 SPRG SKU 27410 Serial Bbl.

DOM

Date Purchased

Where Purchased

Accessories

Original Owner

71254185 EZ 10/19/2005 1:00:44 AM

WAL-MART DC 6003R-REGULAR

Y

CONCERN: FBC

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/710/CF/BA

Settlement

Release of Claims

Release Date

Reimbursement

Cash Settlement Reim. Date Cash Date

APV APV

Per Ilion - Repair @ n/c - goodwill gesture

Repair/Replacement

Repair/Replacement

Cost

Date

\$4

1/25/2012

12/15/11: Mailing ARS & forms. Box order# 1285940. df 1/12/12: Per Ilion - Could not duplicate concern. As a goodwill gesture & to restore confidence in rifle - willing to replace TA, clean & test fire @ n/c. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/10/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 3006 SPRG
	Date Code		EZ
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=7089&Type=Case

1/25/2012

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
Managina	Condition	Select	
Magazine	Box Condition	Slightly Worn; Functioning	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		M/710 SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	N/A
Sear	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	10313	False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	Select	4.5#
1115501	Altered	False	
	Sub-Assembly	Other Remington	

Remington_®

EZ10/0 4.5±

7089

December 14, 2011

Russell Barnhart 6608 Springdale Hunters Rd. Hunters, WA 99137 Phone: 509-722-3112

Ref: #7089, Model 710, Serial #71254185

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination and service request. A box will arrive separately.

Please include a copy of this <u>letter and service request</u> to put inside the shipping container. The letter and service request inside are important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results. I will contact you once I get the report.

I hope this action will keep you a loyal Remington customer.

Sincerely,
Dell Fulcher
Consumer Affairs Administrator
Remington Arms Co., LLC

Phone: 1-800-243-9700 press 0 and ask for ext 8686

Fax: 336-548-7872

enclosure



could not duplicate concern.

As A Good-WillGestune + 70

Lestore confidence in refle

will replace TPA, cleans test

fine at N/C TESTIVII

#760974 JAN 16 2012

	•	٠	٠.	- •	
		,,,	117	11	
•	ŧ	ı	н	11	

Reset

Number: Rem. 7/0	Serial Number: 7/25 4/85			
Are you the original owner?: 🂢 YES □ NO				
Name: Pussell D. Barnhart	Date of Purchase:			
6608 Springdale Hunters 1820				
City: Hunters State: Vost Zip: 99/37				
Phone (Daytime): 509 722 3112 Fax: N/A				
E-mail Address:(if e-mail address is provided, notification of receipt and shipment will be sent)				
E-mail Address: ☐ I would like to receive future e-mail updates from Remington.				
Please describe your proble				
I fired The rifle and ejected the empty case. When patting a new round,				
more resistence Than rormal When				
The bolt closed completely The rifle				
Ammunition Information:				
Manufacturer:	Type:			
Other (i.e. bullet weight/type, shot size, powder):				
Handload Information:				
Powder Used: INR 4350, Powder Weight: 54 Grains				
Case/Hull Used: My Match.	Primer Used: CCT 200			
Bullet Type/Shot Size: / FD & PP/.	Reloader Used: 17085 Tor			
NossLer				
Firearms Care (Cleaning and Lubrication):				

http://www.remington.com/asp/factory_repair_form.asp

8/25/2011

Brand of cleaning solution used: HOPPRS
How often do you clean the bore? (Months or Number of rounds)
How often do you clean the action? (Months or Number of rounds)
How often do you clean the trigger assembly? (Months or Number of rounds)
Brand of lubricant used:
How often do you lubricate the bore? (Months or Number of rounds)
How often do you lubricate the action? (Months or Number of rounds)
How often do you lubricate the trigger assembly? (Months or Number of rounds)
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? >□ YES XNO
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?)
What were the services performed?)
Ship your INSURED firearm by either UPS or Parcel Post to:
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357
□ WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM. :: Record the serial number of your firearm before sending it.
:: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper

return address will be refused.

:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for

damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)

:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.

12-23-11 Durchased This rifle mariphy for hunting deer and coy of es. and yes the state the 180 gr. Nosshers but, I shay Load This one round. Though I purchased it in defortor. The gan was sighted in with 4 rounds and trosn't been fired Less Than 20 rounds J have several rifles, hand
gars as well as shot gars and I
have been in the field for 60
years. Also I have been reloading
since 1962. have ever experenced. In The Long run it feel that this happened instead of in some ones hand with Little or Limited expenence. A serious accident or death could have occured. RDBamhant

ARS LABEL REQUEST FORM

DATE:	12/15/2011	Service Request #	SR00006763
QUANTITY:	1	WEIGHT PER PACKAGE:	10 LBS
REQUESTED BY:	fulcherdm	email address:	I WILL MAIL LABEL
Business:		Remington Service PO Box 700 Madison, NC 27025-0700 www.remington.com	

LABEL INFORMATION		
MAIL LABEL TO:	RUSSELL BARNHART 6608 SPRINGDALE HUNTERS RD HUNTERS, WA 99137 US SR00006763 Email:	
RETURN ITEM TO:	ILN Arms Services	



4XX596 DEC 15, 2011 ACT WT 10.0 LBS #PK 1 SVC GNDCOM BL WT 10.0 LBS TRACKING# 1Z4XX5969065165061 ALL CURRENCY USI REF 1:SR00006763 REF 2: ALL CURRENCY USD FRT: 3RD HANDLING CHARGE 0.00 SVC T/P USD RS 0.50 SHIPMENT PUB RATE CHARGES: DV 0.00 DC 0.00 COD 0.00 DGD 0.00

AH 0.00 TOT PUB CHG 12.74 PR 0.00 ROD 0.00 PUB+HANDLING 12.74





