Remington Arms Co., Inc. Product Service Legal Case #:7487

Case	Informat	ion
------	----------	-----

Date Opened(PS) Date Closed **Incident Date** Pre Lit Lit Obsolete RE# **Date Opened** 3/15/2012 X 261290 3/8/2012 3/15/2012

Customer Information

Type Business First Name Last Name Street City State Zip Contact H n/a 247 Barton Ferry Rd. Carter Westpoint MS 39773 Incident James E jaca0466@comcast.net

Incident Information

Claims Codes Repair Est. **Medical Treatment Medical Status**

ΡI

Could Not Duplicate Concern PD Cause:4038

Unknown

S Fired on Safe C

Concern: 1028 Fired With Safe ON

SR# 12080 - Reason for Return: Forward to Product Service for Inspection. Service Request Section: Fires when on safety. Has done it twice. Last time the trigger guard broke when it discharged. Was carrying it over shoulder when it discharged. No alterations have been done to the trigger per customer. df

Firearm Information

Mfg. Remington

Type CF/BA

Model/Ga. 710/7MM REM MA

SKU 27412

Bbl. Serial

DOM

Date Purchased

Where Purchased

Accessories

Original Owner

71229876 PZ 6/9/2005 2:27:27 PM

WAL-MART DC 6003R-REGULAR

SCOPE BASE

CONCERN: FIRED ON SAFETY

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/710/CF/BA

Settlement Release of Claims Release Date

Reimbursement

Cash

Cash

Reim. Settlement Date APV Date APV

Per Ilion - Replace w/85635 -M/770, 7MM REM MAG @ n/c

Repair/Replacement Cost

Repair/Replacement

Date

\$167

3/21/12: Per Ilion - Could not duplicate concern. TA has excessive preplay. To restore confidence in rifle. Ilion has ordered a replacement rifle. Ramac 85635 @ n/c. SAP order # 1328230. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		3/15/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		24" 7MM REM MAG
	Date Code		PZ
	Bore Plugged	False	
	Bulged	False	
	Fired	False	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=7487&Type=Case

4/3/2012

	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning]
Bolt	Firing Pin	Slightly Worn; Functioning	1
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	7
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking L	Block Condition	Select	7
	Lug Condition	Slightly Worn; Functioning	7
	Notch Condition	Select	
	Condition	Select	
Magazine	Box Condition	Slightly Worn; Functioning	<u> </u>
	Exterior Condition	Slightly Worn; Functioning	DIRTY,LITE RUSTING
Overall	Stock Condition	Slightly Worn; Functioning	TRIG GUARD BROKEN
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Keceiver	Bulged	False	
Safety	Description		M/710 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS] .
Sear	Lift	Select	N/A
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	116515	False	<u></u>
Trigger	Condition	Slightly Worn; Not Functioning	HAS AN EXCEPTIONAL AMOUNT OF PREPLAY
	Pull	Select	4.5#
	Altered	False	
	Sub-Assembly	Other Remington] ·

Service Request

Remington Service PO Box 700

Date of Request:

Date Printed:

02/07/2012

02/07/2012

Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.remington.com This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service PLEASE RETAIN THIS COPY FOR YOUR RECORDS.

Service Request Number

Serial Number / Description

SR00012080 -

71229876

Model 710 RIFLE

Customer: JAMES CARTER

247 BARTON FERRY RD

WESTPOINT, MS 39773 US

Destination: 14 Hoefler Ave

Email

Ilion, NY 13357 US

Email: JACA0466@COMCAST NET

-Your request for service on the item(s) will be evaluated by our repairman to determine if it is co d under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed

Reason For Return

M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION

fires when on safety. has done it twice. last time, the trigger guard broke when it discharged. w as carrying it over his shoulder when it discharged the last time. no alterations have been done to the trigger assembly or the gun per consumer.

Parts And Service Details

Material

Type

Warranty

Disc Amount



THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the

NECEIVE 1 MAR 2 1 2012

could not dup lical Bycomagnan T.A. has Excessive proplay. To restore confidence in RIPLE WILL replace TPA/CLAN + rust st N/c.

Lephre Stock Sub Total:

Est Sales Tax:

.00 .00

Grand Total: TFZ 30145







