

Remington Arms Co., Inc.  
Product Service  
Legal Case #:7179

## Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
252098	12/30/2011	1/3/2012	1/3/2012				

## Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter		Richard	Rozinek	1403 1st Ave SW	Cedar Rapids	IA	52405		H 319-362-5536 C 319-389-0671

Incident	First Name	Last Name
	Tanner	Rozinek

## Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI cut thumb				
PD	Cause:4038 Could Not Duplicate Concern			
S Fired on bolt closing	Concern:1008 Fired on Bolt Closing		U	
C				

per letter: gun fired when bolt pushed forward. bolt kicked back and split open the top of his thumb. no mention of medical treatment.

## Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	710/270 WIN	27408	71027224	WV	8/28/2001 2:11:16 AM

Date Purchased	Where Purchased	Accessories	Original Owner
	WAL-MART WHSE 6003R - REG		U

CONCERN: FBC

Ammunition Information - None Defined

Other Products Information - None Defined

## Settlement

Remington/710/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Clean and check at n/c						

Repair/Replacement Cost	Repair/Replacement Date
27.00	1/25/2012

per lition: could not duplicate concern. Remover check over & clean tpa. safety check & test fire at n/c

## Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/3/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 270 WIN
	Date Code		WV
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	

Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	--Select--	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	--Select--	
Magazine	Condition	--Select--	
	Box Condition	Missing	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	--Select--	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/710 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	ISS	
Sear	Lift	--Select--	N/A
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	--Select--	4#
	Altered	False	
	Sub-Assembly	Other Remington	

**Richard Rozinek**

**Subject:** FW: Misfire on a Remington Model 710 rifle

**Importance:** High

7179

22"  
WV8/01  
4#

**From:** Richard Rozinek [mailto:glassrooster@monmail.com]

**Sent:** Wednesday, December 21, 2011 11:12 AM

**To:** 'info@remington.com'

**Subject:** Misfire on a Remington Model 710 rifle

**Importance:** High

Dear Sirs,

A few years ago my son, Tanner Rozinek, bought a new Remington Model 710, 270 Win rifle, serial number 71027224. I have taken him out shooting with it a couple times but the rifle has less than 100 rounds through it total. You can take one look at the rifle and tell it is essentially brand new. The last time we went out, on his second shot, when he pushed the bolt forward the rifle went off. Fortunately he had the rifle pointing downrange so no one got shot, but the bolt kicked back and split open the top of his thumb.

I contacted Remington about this and was sent the included return authorization. I have included all the documentation on the rifle I can locate. My son did not register the rifle when he bought it. I cannot locate his receipt but do have the original owner's manual with the registration card and the proof of purchase bar code stickers on the back. I have included a copy of them. The Wal-Mart he bought it at no longer sells guns so they sent all their arms sales documentation to their corporate offices.

Richard Rozinek  
1403 1<sup>st</sup> Ave SW  
Cedar Rapids, Iowa 52405  
Ph (319) 362-5536  
Cell (319) 389-0671

RECEIVED  
JAN - 4 2012  
BY:.....

71027224

Model: 710



RE00252098

could not duplicate concern.  
remove check over & clean TPA.  
safety check & test fire AT  
N/C

#260974

[illegible]

[www.remington.com](http://www.remington.com)

<b>Service Request Number</b>	<b>Serial Number / Description</b>	<b>Date of Request:</b>	12-14-2011
SR06006628	71027224	<b>Date Printed:</b>	12-14-2011

  

<b>Customer:</b> TANNER ROZINEK 1403 1ST AVE SW CEDAR RAPIDS, IA 52405 US	<b>Destination:</b> Arms Services 14 Hoedler Ave Elion, NY 13357 US
--	--

  

Email: glassrooster@mcmmail.com      Email:

---

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

---

**Reason For Return**

M125 - FORWARD TO PRODUCT SERVICE FOR INSPECTION  
M310 - PERFORM SAFETY CHECKS ON TRIGGER ASSEMBLY

---

**Service Request Section**

---

<b>Parts And Service Details</b>								
<b>Material</b>	<b>Type</b>	<b>Description</b>	<b>Qty Needed</b>	<b>Warranty</b>	<b>Price</b>	<b>Disc</b>	<b>Amount</b>	

  
  
  

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the

  
  
  

<b>Sub Total:</b>	.00
<b>Est Sales Tax:</b>	.00
<b>Grand Total:</b>	\$ .00

118

Remington

ORDER NO. 27408

BARREL LENGTH 22"

CAPACITY 4

71027224



UPC



Model 710 W/Scope  
Bolt Action Centerfire Rifle  
22" Barrel .270 Cal. W/4 Shot Mag Box

ASK FOR PACING CARTON  
-OWNER'S MANUAL & WARRANTY CARD

02 FORM









