PrintDisplay Page 1 of 3

> Remington Arms Co., Inc. **Product Service** Legal Case #:8207

Case Information

Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete RE# Date Opened

12/4/2012 12/4/2012 12/3/2012 291130

Customer Information

First Name City State Zip Age **Business** Last Name Street Contact Type W 606-436-3552 Rolane Applianc 2108 N. Main St Hazard KY 41701 Reporter Rolane Appliance Gary F 606-436-6062

Incident Information

Codes Repair Est. Medical Treatment Medical Status Claims

ΡI

Cause:4013 Broken or Missing Parts PD Unknown Concern: 1008 Fired on Bolt Closing S Fired when closing bolt

11/27/12 Per call from Gary, his customer bought this rifle from Walmart about 3 years ago. Recently it fired when he closed the bolt. Also, it appears broken behind the bolt.cm

Firearm Information

Serial Bbl. **DOM** Mfg. Type Model/Ga. SKU Remington CF/BA 710/7MM REM MA 27412 71341291 RA 11/28/2006 5:14:25 PM

Date Purchased Where Purchased Accessories Original Owner

WAL-MART STORE 0324 SCOPE BASE Y

CONCERN: FBC

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/710/CF/BA

Reim. Cash Cash Settlement Reimbursement Date Release of Claims Release Date Date Settlement APV APV

Per Ilion, replace TPA, check over and test at no charge

> Repair/Replacement Repair/Replacement Cost Date

41.15

12/10/2012

11/27/12 Will fax ARS to Gary.cm 12/10/12 Per Ilion, trigger plate broken. Replace TPA, check over and test at no charge.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		12/4/2012
Examination Product Type			RF
11	Action Type		A
	Assigned To		J.BALIO

PrintDisplay Page 2 of 3

Cause	4013	Broken or Missing Parts	TRIG PLATE BROKEN
Barrel	Description		24" 7MM REM MAG
	Date Code		RA
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzlc/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Condition	Select	
Magazine	Box Condition	Slightly Worn; Functioning	
	Exterior Condition	Slightly Worn; Not Functioning	
Overali	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	Select	N/A
	Notch	Slightly Worn; Not Functioning	
	Tests	Test Fired	False
Feeding	1 5313		

Test		False	
Trigger	Condition	Abused; Not Functioning	PLATE IS CRACKED AND RIGHT SIDE PLATE DAMAGED, APPEARS FROM CONTACT WITH FIRING PIN HEAD WILL FOLL
	Pull	Select	N/A
	Altered	False	
	Sub-Assembly	Other Remington]

Service Request

Remington Service PO Box 700

Parts and Repairs: P:800-243-9700/F:336-548-7801

Madison, NC 27025-0700 www.remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

Service Request Number | Serial Number / Description

SR00036483

71341291

Model 710 RIFLE

Email:

Customer:
ROLANE APPLIANCE C/O GARY 2108 N. MAIN ST HAZARD, KY 41701 US

Date of Request: 11/27/2012

Date Printed: 11/27/2012

Destination: Arms Services 14 Hoeffer Avc Ilion, NY 13357 US

Email:

Your request for service on the item(s) will be evaluated by our repairmen to determine if it is covered under our warrenty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Prod Serv #8207

Material Type Description City
Needed

Model:



DEC 0 5 2012

Tizig. Plate Droken. Pap. TEA, check oven + Test N/C

230145

THIS IS NOT AN INVOICE. This is a pro-estimate to repair, recondition, or replace the stem(s) being sent based on the conversation with our representative,

Sub Total: Est Sales Tax: .00 .00

Grand Total:

\$.00

I Boucht This GUN ABOUT 21/2-3 years
AGO AT WAL MANT IN Day Ridle Ky.
I have Shot This GON ABOUT LESS show a
Box of Shills through . J. When you put the
BOLTINAGON FIRES!! It LOOKE Like The
GUN. 5 Broke Below the BULT AUST.
Please Repar on Replace ps soon As passible
I do. NOT have Egles RCIEPT.
Charles Fugare
glersa Send BACK To
Charles Fugate
P: 80× 27
Cembs Ky 41729
C·W438-8721
and the second of the second o
######################################
CONTROL SE
For the contract of the contra
PORTION AND RELIGIOUS ASSESSMENT OF THE APPROXIMATION OF THE APPROXIMATI

Remington.

To: Cary Date: 1/27/12 Company: Rolane Appliance From: Christy Mitchell Fax No.: 606-436-6062 Fax No.: Phone No.: Phone No.: Number of pages including Cover Sheet: COMMENTS:

PRIVILEGED AND CONFIDENTIAL

This facsimile is intended only for the use of the individual or entity to which it is addressed and may contain information that is privileged, confidential and exempt from disclosure. If you are not the intended recipient please do not disseminate, distribute, or copy this communication. Instead, please notify the sender immediately by return fax or by telephoning the number above and discard all copies of this fax.


Remington Arms Company, Inc. ● 870 Remington Drive ● P.O. Box 700 ● Madison, NC 27025-0700 Phone 336-548-8700 ● www.remington.com

ROLANE APPLIANCE C/O GARY HAZARD KY 41701 10 LBS

1 OF 1

RS


SHIP TO:
PROD SERV #8207
ARMS SERVICES
14 HOEFLER AVE
ILION NY 13357



NY 135 0 - 01

UPS GROUND

TRACKING #: 1Z 4XX 596 90 6609 4243



BILLING: 3RD PARTY DESC: Firearms RETURN SERVICE

REF 1:SR00036483

W8 15.0.16 Zebra 2P Ser 33.0A 10/2012



SET MITTE CONTRACTED approach UPS teams and explor of landarium of landary, where allowed by the Lothers contributes UPS to act as innerenties event for expert excess and contract programs if experted is on the US. Accordance with the Export Approximations that the contractions, which explore a majority and the contraction of the contractions are supported in the Contraction of the Contract

Please send your firearm back via a traceable method of shipping to the address below.

This Service Request number is only valid for this return.

Please follow these guidelines:

- Include a copy of your proof of purchase to assist in the evaluation of your repair
- Record your serial number for future reference
- Remove <u>any</u> accessories (sling, scope, scope mounts, case, etc.)
 unless these items are needed to assist in the evaluation.
- Properly package your <u>unloaded</u> firearm. Do not ship in your hard case (note: Original boxes are not returned with repair)
- Do not send live/loaded or spent ammunition with your firearm.
- Please package the ammunition in a secure carton or box.
- The package should be stuffed to prevent movement.
- Include service request number.
- Shipment of live ammo must be via U.P.S. only.
- Please advise your local U.P.S. mailing center of the contents so that a special Other Regulated Materials-Domestic (ORM-D) label can be applied.

Please let us know of any address change requests by email or phone. Our returns process will take approximately 2-3 weeks to complete and a confirmation email will be sent once we have shipped your firearm.

Should you have any further questions or concerns please don't hesitate to contact us via email (<u>info@remington.com</u> << mailto:<u>info@remington.com</u> >>) or by phone at 800-243-9700, M-F 9am - 5pm, EST. We look forward to helping you resolve this issue!

(ear new)
(cut here)
Mailing Label:

Arms Services SR# SR00036483 14 Hoefler Ave Ilion, NY 13357 US

Email:

Attn: Prod Serv #8207



TRANSMISSION VERIFICATION REPORT

: 11/27/2012 18:50

TIME : 11/27/2012 18 NAME : FAX : 3365487823 TEL : SER.# : BROC0J148005

DATE, TIME FAX NO./NAME DURATION PAGE(S) RESULT MODE

11/27 18:50 16064365062 00:00:46 04 UK STANDARD ECM

Remington.

FACSIMILE TRANSMITTAL SHEET						
То:	Cary	Date:	11/27/12			
Company:	Rolone Appliance 606-436-6062	From:	Christy Mitchell			
Fax No.:	606-436-6062	Fax No.:				
Phone No.:		Phone No.:				
Number of p	Number of pages including Cover Sheet:					
COMM	ENTS:					
			·			

ARS LABEL REQUEST FORM

DATE:	11/27/2012		Service Request #	SR00036483
QUANTITY:	1		WEIGHT PER PACKAGE:	10 LBS
REQUESTED BY:	mitchellcs		email address:	
Business:		Remington Servic PO Box 700 Madison, NC 270 www.remington.	25-0700	
			FORMATION	
MAIL LABEL	TO:	ROLANE APPLIA C/O GARY 2108 N. MAIN ST SR00036483 HAZARD, KY 4 Email:	Γ	
RETURN ITE	м то:	ILN Arms Services		
L		TRACKING# 1Z4XX596906 REF 1:SR00036483 REF 2:	6094243 ALL CURRENC	CY USD GO GO

ATTN: Prod Serv #8207