

Remington Arms Co., Inc.  
Product Service  
Legal Case #:7643

## Case Information

| RE#    | Date Opened | Date Opened(PS) | Date Closed | Incident Date | Pre Lit | Lit | Obsolete |
|--------|-------------|-----------------|-------------|---------------|---------|-----|----------|
| 266735 | 5/7/2012    | 5/8/2012        | 5/8/2012    |               |         |     | X        |

## Customer Information

| Type     | Business         | First Name | Last Name       | Street              | City      | State | Zip   | Age | Contact        |
|----------|------------------|------------|-----------------|---------------------|-----------|-------|-------|-----|----------------|
| Reporter | Da-Mar Gunsmiths |            | Da-Mar Gunsmith | 2686 East Brutus St | Weedsport | NY    | 13166 |     | W 315-834-9156 |

## Incident Information

| Claims             | Codes                      | Repair Est.                                          | Medical Treatment | Medical Status |
|--------------------|----------------------------|------------------------------------------------------|-------------------|----------------|
| PI<br>PD<br>S<br>C | Cause:4038<br>Concern:1008 | Could Not Duplicate Concern<br>Fired on Bolt Closing | Unknown           |                |

5/18/12 Per letter with rifle, the owner had the gun fire when he closed the bolt. The Gun Works in Verona told him the factory will install a new trigger for about \$20.cm

## Firearm Information

| Mfg.           | Type            | Model/Ga.   | SKU            | Serial | Bbl. | DOM      |
|----------------|-----------------|-------------|----------------|--------|------|----------|
| Remington      | CF/BA           | 721/280 REM | n/a            | 432938 | AA   | 1/1/1954 |
| Date Purchased | Where Purchased | Accessories | Original Owner |        |      |          |
|                |                 |             | U              |        |      |          |

CONCERN: FBC

Ammunition Information - None Defined

Other Products Information - None Defined

## Settlement

Remington/721/CF/BA

| Settlement                                                    | Release of Claims       | Release Date            | Reimbursement | Cash Settlement | Reim. Date APV | Cash Date APV |
|---------------------------------------------------------------|-------------------------|-------------------------|---------------|-----------------|----------------|---------------|
| Per Ilion, replace TPA, clean and check over under BLSM price |                         |                         |               |                 |                |               |
|                                                               | Repair/Replacement Cost | Repair/Replacement Date |               |                 |                |               |
|                                                               | 7.82                    | 5/18/2012               |               |                 |                |               |

5/18/12 Per Ilion, replace TPA, clean and check over under BLSM price.cm

## Examination[Remington/CF/BA]

| Part        | Sub-Part     | Code | Comment  |
|-------------|--------------|------|----------|
| Examination | Examiner     |      | B.TRAVIS |
|             | Exam Date    |      | 5/8/2012 |
|             | Product Type |      | RF       |

|              |                        |                             |                        |
|--------------|------------------------|-----------------------------|------------------------|
|              | Action Type            |                             | A                      |
|              | Assigned To            |                             | T.NAGLE                |
| Cause        | 4038                   | Could Not Duplicate Concern |                        |
| Barrel       | Description            |                             | 22" 280 REM            |
|              | Date Code              |                             | AA                     |
|              | Bore Plugged           | False                       |                        |
|              | Bulged                 | False                       |                        |
|              | Fired                  | False                       |                        |
|              | Fired while Obstructed |                             |                        |
|              | Muzzle/Crown Condition | Slightly Worn; Functioning  |                        |
| Bolt         | Firing Pin             | Slightly Worn; Functioning  |                        |
|              | Shroud                 | Slightly Worn; Functioning  |                        |
|              | Face                   | Slightly Worn; Functioning  |                        |
|              | Handle                 | Slightly Worn; Functioning  |                        |
|              | Stop                   | Slightly Worn; Functioning  |                        |
| Extractor    | Condition              | Slightly Worn; Functioning  |                        |
|              | Cut Condition          | Slightly Worn; Functioning  |                        |
|              | Ext/Eject Test         | False                       |                        |
| Locking      | Block Condition        | ---Select---                |                        |
|              | Lug Condition          | Slightly Worn; Functioning  |                        |
|              | Notch Condition        | ---Select---                |                        |
| Overall      | Exterior Condition     | Slightly Worn; Functioning  | RECEIVED UNASSM. L/STK |
|              | Stock Condition        | ---Select---                |                        |
|              | Fore End Condition     | ---Select---                |                        |
| Receiver     | Condition              | Slightly Worn; Functioning  |                        |
|              | Bulged                 | False                       |                        |
| Safety       | Description            |                             | M/721 BOLT LOCK SAFETY |
|              | Function               | Like new; Functioning       |                        |
|              | Sub-Assembly           | Non-ISS                     |                        |
| Sear         | Lift                   | ---Select---                | N/A                    |
|              | Notch                  | Slightly Worn; Functioning  |                        |
| Feeding Test | Tests                  | Test Fired                  | False                  |
|              |                        | False                       |                        |
| Trigger      | Condition              | Slightly Worn; Functioning  | REC'D UNASSM           |
|              | Pull                   | ---Select---                | N/A                    |
|              | Altered                | False                       |                        |
|              | Sub-Assembly           | Other Remington             |                        |

7643

2211  
AA1/54

Da-Mar Gunsmith's  
2686 East Brutus St  
Weedsport, NY 13166  
(315) 834-9156



REMINGTON ARMS SERVICE  
14 HOCKLER AVE  
ILION, N.Y. 13057

05/01/12

GENTLEMEN:

ENCLOSED IS A REMINGTON 721-280 CAL  
# 432938. THE OWNER HAD THE GUN FIRE WHEN  
HE CLOSED THE BOLT. THE GUN WORKS IN VERONA  
TOLD ME YOU (THE FACTORY) WILL INSTALL A NEW  
TRIGGER FOR ABOUT \$20.00. PLEASE DO SO. I HAVE  
ENCLOSED THE OLD TRIGGER AND PARTS. PLEASE CALL  
ME FOR CREDIT CARD PAYMENT. 315-834 9156.

432938

Model:  721



RE00266735

THANK YOU  
DAVID A. KLOTZ

Replace TPA, clean + check over  
under 2LP for \$20. + shipping

RECEIVED  
MAY 15 2012

BY: .....



