

Remington Arms Co., Inc.
Product Service
Legal Case #:7657

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
267023	5/9/2012	5/10/2012	5/10/2012				X

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Joseph	Rinaggio	239 Wood Acres Dr	East Amherst	NY	14051		

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4015	Improper Maintenance		
S	Fired without pulling the trigger	Concern:1025	Unexplained Discharge - No Mention of Safety Position	Unknown
C				

5/18/12 Per note on SR, customer states the rifle will fire without pulling the trigger.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	721/3006 SPRG	n/a	436229	PH3	6/1/1961
Date Purchased	Where Purchased	Accessories	Original Owner			
		SCOPE BASE,AFT MKT STK	U			

CONCERN:FIRES WITHOUT PULLING TRIGGER

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/721/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean, test at BLSM price						

Repair/Replacement Cost	Repair/Replacement Date
27.82	5/18/2012

5/18/12 Per Ilion, trigger assm dirty/rusty. Trigger will not move. Replace TPA, clean, test at BLSM price.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		5/10/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE

Cause	4015	Improper Maintenance	
Barrel	Description		22" 3006 SPRG
	Date Code		PH3
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	--Select--	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	--Select--	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	AFT MKT
	Fore End Condition	--Select--	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/721 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	--Select--	N/A
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	DIRTY,RUSTY TRIG WILL NOT MOVE,FROZEN TO SIDE PLATES
	Pull	--Select--	N/A
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	Other Remington	

Non-Remington Components	Description	SCOPE BASE,AFT MKT STK
-----------------------------	-------------	------------------------

Serial Number: 436229
Model: 721



RE00267023

RECEIVED
MAY 15 2012

Refresh

Close

THURSDAY, MAY 10 2018 SRP

55

Thursday, May 10 2012

4:15 AM



436224
72
REMINGTON-UNION
MODEL 760
NEW YORK, N.Y.





