

Remington Arms Co., Inc.
Product Service
Legal Case #:7788

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
273511	6/29/2012	7/16/2012	7/16/2012				X

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Tamarack Armory	Mike	Tamarack Armory	20817 Alden St	Meadville	PA	16335		W 814-336-2688 E tamarackarmory@yahoo.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI PD S C	Cause:4038 Could Not Duplicate Concern Concern:1007 Fired on Safe Release		Unknown	

Fired when safety was moved

7/23/12 Per note on SR, customer states the rifle fired when safety is moved.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	722/222 REM	n/a	223605	XXX	12/1/1951
Date Purchased	Where Purchased	Accessories	Original Owner			
			U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/722/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean, test at BLSM program price						
	Repair/Replacement Cost	Repair/Replacement Date				
	27.82	7/23/2012				

7/23/12 Per Ilion, could not duplicate concern. Replace TPA, clean, test at BLSM program price.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		7/16/2012
	Product Type		RF

	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		26" 222 REM
	Date Code		XXX
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/722 BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	.012
	Notch	Slightly Worn; Functioning	
Feeding Test	Tests	Test Fired	False
		False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	---Select---	4#
	Altered	False	
	Sub-Assembly	Other Remington	

Madison, NC 27025-0700.

Parts and Repairs: P:800-243-9700 F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. **ENCLOSE THIS DOCUMENT WITH YOUR RETURN.**

2611
12/51
4#
012


Service Request Number 00022568	Serial Number / Description 223605 Model 722 Center Fire	Date of Request: 06-20-2012 Date Printed: 06-22-2012
Customer: TAMARACK ARMORY 20817 ALDEN STREET ATTN MIKE MEADVILLE, PA 16335 US Email: tamarackarmory@yahoo.com		Destination: Arms Services 14 Hoefler Ave Llano, NY 13357 US Email:

Our request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

7788

Reason For Return
240 - BOLT LOCK SAFETY MODIFICATION

Service Request Section
Customer states the rifle fired when safety is moved.



Parts And Service Details							
Material	Type	Description	Qty Needed	Warranty	Price	Disc	Amount
Bolt wrapped IN Bkr towel							
223605 Model: 722							
RE00273511							
US IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the							
could not disp. concern up to TPA clean fast under BCP Ron & 20+ ship							
Quote RECEIVED JUL 9 2012							
BY: _____							
Sub Total: .00 Est Sales Tax: .00 Grand Total: \$.00							





