Remington Arms Co., Inc. Product Service Legal Case #:8044

Case Information

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Lit Obsolete Pre Lit 285527 10/15/2012 10/16/2012 10/16/2012

Customer Information

Type **Business** First Name Last Name Street City Zip Contact State Age Incident 14120 Clinton Rd. Chris Chwalinski North Little Rock AR 72118 H 501-851-3358

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

ΡI

PD Cause: 4038 Could Not Duplicate Concern Concern: 1007 Fired on Safe Release

Unknown

S FSR

SR# 3957 - Service Request Section: Per Consumer, gun went off when safety was flipped off. df

Firearm Information

Mfg. Remington

Type CF/BA

Model/Ga. 770/3006 SPRG

SKU 85633

Serial Bbl. M71589794 LE

DOM 2/17/2010 12:21:24 PM

Date Purchased

Where Purchased SPORTS SOUTH LLC

Accessories SCOPE BASE Original Owner U

CONCERN: FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/770/CF/BA

Settlement

Release of Claims

Release Date

Reimbursement

Cash Settlement

Reim. Date Cash Date APV APV

Per Ilion - Replace TA & test @ n/c

> Repair/Replacement Cost

Repair/Replacement Date

\$41

10/17/12: Per Ilion - Could not duplicate concern. To restore confidence in rifle, will replace TA, check over & test at n/c. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		10/16/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 3006 SPRG
	Date Code		LE
	Bore Plugged	False	
	Bulged	Falsc	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	

lı	1		
Bolt	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	Select	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
Magazine	Condition	Select	
	Box Condition	Slightly Worn; Functioning	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD SAFETY
	Function	Like new; Functioning	
Sear	Lift	Select	N/A
	Notch	Slightly Worn; Functioning	
	T	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	Select	4#
	Altered	False	
	Sub-Assembly	Other Remington	

Service Request

Remington Service PO Box 700

Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

Service Request Number | Serial Number / Description

SR00003957

M71589794

Model 770 RIFLE

Customer

CHARLES CHWALINSKI 14120 CLINTON ROAD

NORTH LITTLE ROCK, AR 72118 US

Email:

Date of Request: 11/15/2011

Printed: 11/16/2011

Destination:

Arms Services 14 Hoefler Ave

Ilion, NY 13357 US

Email:

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return

M310 - PERFORM SAFETY CHECKS ON TRIGGER ASSEMBLY

Service Request Section

PER CONSUMER, GUN WENT OFF WHEN SAFETY WAS FLIPPED OFF.

Qty Warranty Needed

Price

Disc Amount

Coald not duplishe eaucen.
To restore confidence in rifle
will replace TPA, checkoused
rest AT N/C

260924

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) being sent based on the conversation with our representative.

Sub Total:

.00

Est Sales Tax:

.00

Grand Total:

\$.00