Remington Arms Co., Inc. Product Service Legal Case #:8133

Case Information

 RE#
 Date Opened
 Date Opened(PS)
 Date Closed
 Incident Date
 Pre Lit
 Lit
 Obsolete

 290494
 11/27/2012
 11/8/2012
 12/10/2012
 11/8/2012
 11/8/2012

Customer Information

Business First Name Last Name Zip Type Street City State Contact Age H 606-754-3176 Incident Freeda Thacker 1110 Harless Creek Regina KY 41559 E freeda.thacker@cebridge.net

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PI hit finger

PD Cause: 4038 Could Not Duplicate Concern

S Fired on safety release Concern: 1007 Fired on Safe Release

N

С

11/8/12 Per call from Freeda, when releasing the safety today the rifle fired. It hit her finger when it happened. She does not want this rifle. Also the bolt is hanging up.

Firearm Information

Mfg. Type Model/Ga. SKU Serial Bbl. DOM
Remington CF/BA 770/3006 SPR 85633 M71786737 AG 3/5/2012 9:34:43 AM
Pate Purchased Where Purchased Accessories Original Owner

Date Purchased VAL-MA

WAL-MART SUPERCENTER 1505 SCOPE, BASE, RINGS

Y

CONCERN: FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/770/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Reim. Date APV

Replace TPA, test no charge to restore confidence

Repair/Replacement Cost Repair/Replacement Date

73.65

12/14/2012

11/8/12 Emailing ARS.cm 11/14/12 Left msge to call me. UPS label has not been used yet.cm 12/5/12 Left voice msge regarding inspection. Offered to replace TPA as goodwill and test no charge to restore confidence. Will not replace when no parts out of spec and could not duplicate.cm 12/10/12 Replace TPA, test no charge to restore confidence.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		11/29/2012
	Product Type		RF
	Action Type		Α
	Assigned To		J.BALIO
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 3006 SPRG
	Date Code		AG
	Bore Plugged	False	
	Bulged	False	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=8133&Type=Case

12/14/2012

P

	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Like new; Functioning	
Bolt	Firing Pin	Like new; Functioning	
	Shroud	Like new; Functioning	
	Face	Like new; Functioning	
	Handle	Like new; Functioning	
	Stop	Like new; Functioning	
	Condition	Like new; Functioning	
Extractor	Cut Condition	Like new; Functioning	
	Ext/Eject Test	False	
	Block Condition	Sclect	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
· · · · · · · · · · · · · · · · · · ·	Condition	Select	
Magazine	Box Condition	Like new; Functioning	
	Exterior Condition	Like new; Functioning	
Overall	Stock Condition	Like new; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Like new; Functioning	
Receiver	Bulged	False	
	Description		STANDARD SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	Select	N/A
	Notch	Like new; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
	Condition	Like new; Functioning	
Tricar	Pull	Select	4.5#
Trigger	Altered	False	
	Sub-Assembly	Other Remington	

Service Request

Remington Service PO Box 700



Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700/F:336-548-7801 www.remington.com This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT

Service Request Number SR00034453

WITH YOUR RETURN.

Serial Number / Description

M71786737

Model 770 RIFLE

Customer: FREEDA THACKER 1110 HARLESS CREEK REGINA, KY 41559 US

Emnil: freeda.thacker@cebridge.net

Date of Request: 11/08/2012 Date Printed: 11/08/2012

Destination: Arms Services 14 Hoefler Ave Ilion, NY 13357 US

Email:

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firems will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION

Prod Serv #8133

聞M71786737

BY:

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) being sent based on the conversation with our representative.

Sub Total:

.00

Est Sales Tax:

.00

Grand Total:

\$.00

Service Request

Remington Service PO Box 700



Madison, NC 27025-0700

ATTN: Prod Serv #8133

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service.PLEASE RETAIN THIS COPY FOR YOUR RECORDS.

Service Request Number SR00034453 Customer: FREEDA THACKER 1110 HARLESS CREE REGINA, KY 41559 Email: freeda thacker@ Your request for service on the returned. If not, you will be co	US	to determine if it is covered u	ination: Arms Services 14 Hoefler Ave Ilion, NY 13357 Email: nder our warranty pol	US	rinted:	11/08/20 11/08/20 will be repa	
	PRODUCT SERVICE FOR INSPECT	ION		7		1 2 2 2	\$9.00
Service Request Section : Prod Serv #8133		<u> </u>			\		28 - 1 2 4 4 1 18,45 22 5 2
Parts And Service Details Material Type	Description	Qty Needed	Warranty		Price	Disc A	mount
THIS IS NOT AN INVOICE. I being sent based on the conver	This is a pre-estimate to repair, recondition, sation with our representative.	or replace the item(s)	-		otal; les Tax: Total:		.00 .00 \$.00

Please send your firearm back via a traceable method of shipping to the address below.

"This Service Request number is only valid for this return.

Please follow these guidelines:

- Include a copy of your proof of purchase to assist in the evaluation of your repair
- Record your serial number for future reference
- Remove <u>any</u> accessories (sling, scope, scope mounts, case, etc.)
 unless these items are needed to assist in the evaluation.
- Properly package your <u>unloaded</u> firearm. Do not ship in your hard case (note: Original boxes are not returned with repair)
- Do not send live/loaded or spent ammunition with your firearm.
- Please package the ammunition in a secure carton or box.
- The package should be stuffed to prevent movement.
- Include service request number.
- Shipment of live ammo must be via U.P.S. only.
- Please advise your local U.P.S. mailing center of the contents so that a special Other Regulated Materials-Domestic (ORM-D) label can be applied.

Please let us know of any address change requests by email or phone. Our returns process will take approximately 2-3 weeks to complete and a confirmation email will be sent once we have shipped your firearm.

Should you have any further questions or concerns please don't hesitate to contact us via email (<u>info@remington.com</u>>>) or by phone at 800-243-9700, M-F 9am - 5pm, EST. We look forward to helping you resolve this issue!

(cut here)	 	
_		
Mailing Label:		

Arms Services SR# SR00034453 14 Hoefler Ave Ilion, NY 13357 US

Email:

Attn: Prod Serv #8133



ARS LABEL REQUEST FORM

DATE:	11/08/2012	Service Request #	SR00034453
QUANTITY:	1	WEIGHT PER PACKAGE:	10 LBS
REQUESTED BY:	mitchellcs	email address:	
-			
Business:		Remington Service PO Box 700 Madison, NC 27025-0700 www.remington.com	

LABEL INFORMATION

	LABEL INFORMATION
MAIL LABEL TO:	FREEDA THACKER 1110 HARLESS CREEK REGINA, KY 41559 US SR00034453 Email: freeda.thacker@cebridge.net
RETURN ITEM TO:	ILN Arms Services



4XX596 NOV 9, 2012 ALL CURR USD 1 G
SVC GNDCOM ACT UT 10.0 LBS
TRACKING# 1Z4XX5969067778502
REF 1:SR00034453
REF 2:

HANDLING CHARGE 0.00
SINGLE-PIECE PUB RATE CHRGS: SVC T/P USD
DV 0.00 COD 0.00 RS 0.50
DC 0.00 DGD 0.00 SD 0.00
GM 0.00 PR 0.00 SP 0.00
TOT PUB CHG 9.69 PUB+HANDLING 9.69

ATTN: Prod Serv #8133