

Remington Arms Co., Inc.
Product Service
Legal Case #:8190

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
290142	11/21/2012	11/26/2012	11/26/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Larry	Adams	3145 Southern Ave	Kingman	AZ	86401		E lnadams25@yahoo.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		
S	Gun fired	Concern:1025	Unexplained Discharge - No Mention of Safety Position	Unknown
C				

12/10/12 Per note on SR, states gun fired and wants safety modification.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/243 WIN	n/a	6351600	DU	9/1/1971
Date Purchased	Where Purchased	Accessories	Original Owner			
	JONES DIST PHOENIX ARIZ	TWO PIECE BASE	U			

CONCERN: GUN FIRED

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean, test at BLSM program price						

Repair/Replacement Cost	Repair/Replacement Date
29.44	12/10/2012

12/10/12 Per Ilion, could not duplicate concern. Trigger assm dirty. Replace TPA, clean, test at BLSM program price.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		11/26/2012
	Product Type		RF
	Action Type		A
	Assigned To		J.BALIO

Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 243 WIN
	Date Code		DU
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
Bolt	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
Extractor	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
Locking	Ext/Eject Test	False	
	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
Overall	Notch Condition	---Select---	
	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
Receiver	Fore End Condition	---Select---	
	Condition	Slightly Worn; Functioning	
Safety	Bulged	False	
	Description		BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Sub-Assembly	Non-ISS	
	Lift	---Select---	.006
	Notch	Slightly Worn; Functioning	
Feeding Test	Tests	Test Fired	False
		False	
Trigger	Condition	Slightly Worn; Functioning	VERY DIRTY
	Pull	---Select---	5.5#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

Service Request

Remington Service
PO Box 700

Madison, NC 27025-0700



7211

049/
5.54
1006

Parts and Repairs: P:800-243-9700 F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. **ENCLOSE THIS DOCUMENT WITH YOUR RETURN.**

Service Request Number
SR00034267

Serial Number / Description
6351600
Model 700243

8190

Date of Request: 11-07-2012
Date Printed: 11-07-2012

Customer:
LARRY ADAMS
3145 SOUTHERN AVENUE
KINGMAN, AZ 86401 US

Destination:
Arms Services
14 Hoefler Ave
Ilion, NY 13357 US

Email: lmadams25@yahoo.com

Email:

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return
M240 - BOLT LOCK SAFETY MODIFICATION

Service Request Section
STATES GUN FIRED AND WANTS SAFETY MODIFICATION

Material	Type	Description	Qty Needed	Warranty	Price	Disc	Amount
----------	------	-------------	------------	----------	-------	------	--------

Serial Number:

6351600

Model: 700



RE00290142

RECEIVED
NOV 27 2012

could not be repaired
T.A. dirty. Replace IPA, clean
& test under BCP for 20+

Q

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the

Sub Total: .00
Est Sales Tax: .00
Grand Total: \$.00





