

Remington Arms Co., Inc.
Product Service
Legal Case #:7908

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
280875	9/4/2012	9/5/2012	9/5/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Michael E	Bailey	PO Box 322 816 Rock Cave Rd	Rock Cave	WV	26234		

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4006 Altered Adjustments or Components		Unknown	
S	Fires when moving to Safe Concern: 1028 Fired With Safe ON			
C				

9/21/12 Per note with rifle, when you work the bolt and it is on safety, it will not fire. When you put it on fire, it still will not fire, but if you shove it back to safety, it will drop the firing pin.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/222 REM MA	n/a	75044	OK	7/1/1963
Date Purchased	Where Purchased	Accessories	Original Owner			
		TWO PIECE BASE	U			

CONCERN: FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Replace TPA, clean, test at BLSM program price						
	Repair/Replacement Cost	Repair/Replacement Date				
	29.44	9/21/2012				

9/21/12 Per Ilion, trigger assm set screws altered and trigger is not returning under sear. Replace TPA, clean, test at BLSM program price.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		9/5/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4006	Altered Adjustments or Components	
Barrel	Description		24" 222 REM MAG
	Date Code		OK
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Worn; Not Functioning	
	Stock Condition	Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.003
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	TRIG NOT RETURNING UNDER SEAR WILL FOLLOW DOWN
	Pull	---Select---	1#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

August 27, 2012

7908

24"
OK 7/6:
1#
1003

Michael E. Bailey

816 Rock Cave Road

P.O. Box 322

Rock Cave, WV 26234

SR#SR00027098

Description of problem:

When you work the bolt and it is on safety, it will not fire. When you put it on fire, it still will not fire, but if you shove it back to safety, it will drop the firing pin. I believe it may be a problem in the trigger mechanism.

Thank you,

Michael E Bailey

Michael E. Bailey

RECEIVED
SEP 17 2012

BY:.....

T.A. set screws A / Bent & Trig
is not returning under gear.
Replace FPA, clean rest under
BCP Lock 20. +

Q

Serial
Number:

75044

Model: 700



RE00280875





