

Remington Arms Co., Inc.
Product Service
Legal Case #:7804

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
274986	7/20/2012	7/23/2012	7/23/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Barney's of Lafayette		Barney's	218 Four Park Rd	Lafayette	LA	70507		W 337-896-3667
Incident		Jim	Smithey	212 Sunflower Rd	Opelousas	LA	70570		H 337-543-5448 E prarieronde@gmail

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD				
S	Fired when bolting a round	Cause:4038 Could Not Duplicate Concern Concern:1008 Fired on Bolt Closing	Unknown	
C				

8/6/12 Per letter with rifle, Smithey bought the rifle around the mid-80's. Not long after that he loaned it to a friend and the friend came back after harvesting a deer and asked if he had ever had it fire when bolting another round. Smithey told him he hadn't. A couple of yrs later it happened to Smithey but he dismissed it until recently someone asked if his rifle had ever discharged without touching the trigger. He uses it every year and wants to have it inspected to ensure it is safe.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/270 WIN	25771	B6727653	OF	7/1/1985
Date Purchased	Where Purchased	Accessories	Original Owner			
	WAL-MART STORE 0543 70570	SCOPE BASE	U			

CONCERN:FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, offer to replace TPA, clean, test fire at 1/2 normal cost						
Repair/Replacement Cost	Repair/Replacement Date					

8/6/12 Per Ilion, could not duplicate concern. Trigger assembly dirty and sticky, parts work sluggish. Can offer to replace TPA, clean, test fire at 1/2 normal cost. Customer requested that we return as received on 7/23.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		7/23/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4015	Improper Maintenance	
	Description		22" 270 WIN
	Date Code		OF

Barrel	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.010
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY,STICKY
	Pull	---Select---	4#
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		SCOPE BASE

22"
0F7/85
4#
1010

7804

To Remington Company,


I bought this firearm SN:B6727653 Model 700 chambered .270 win. Sometime in the Mid 80's.

Sometime after that I'd say with the first or second year I loaned the rifle to a friend. He returned the same afternoon to return it. He had harvested a deer, then asked me if the rifle ever went discharged while bolting another round, I told him no. A couple of years later it happened to me, I dismissed both incidences and really forgot about them (never happened since) until someone asked me if my rifle ever discharged without touching the trigger, & then they came back to me.

I use the rifle every year and would like to continue but I need peace of mind for me and my family. One day this firearm which I have harvested many deer with and hopefully many more will someday get passed on to a loved one. I need to know that it is 100% safe, if not it will get traded in on another and it may not be a Remington. I own three other Remington's but not in the 700 model. Two 870's & one nylon.

Please evaluate my rifle,

Jim Smithy



212 Sunflower Rd.

Opelousas, La. 70570

Serial Number:

B6727653


Model: 700



RE00274986

Phone 337-543-5448
email prairieverde@gmail

could not duplicate concern.
T.A. dirty & sticky parts work
sluggish. can often be replaced
T.A., clean & test fire at 1/2
normal cost.



BY:.....

RETURN AUTHORIZATION - LAF-SR00024226

SHIP TO:
 REMINGTON ARMS CO
 870 REMINGTON DR
 PO BOX 700
 MADISON, NC 27025

TEL. 800-243-9700
 FAX 336-548-8798

BILL TO:
 REMINGTON ARMS CO
 870 REMINGTON DR
 PO BOX 700
 MADISON, NC 27025

TEL. 800-243-9700
 FAX 336-548-8798

SHIPPED FROM:
 BARNEYS OF LAFAYETTE
 218 FOUR PARK RD

LAFAYETTE, LA 70507
 U.S.A.

TEL. 337-896-3667
 FAX 337-896-3660

RA DATE 7/16/2012

SHIP DATE 7/16/2012

CANCEL DATE 12/31/2013

TERMS 2.00 NET 30 NET 60

RA REF # 14948

COMMENTS REMINGTON MODEL 700 S/N B6727653
 FIREARM DISCHARGES WITHOUT BOLTING ANOTHER ROUND, WOULD LIKE TRIGGER CHECKED
 FOR SAFETY PURPOSES.
 PLEASE CONTACT ME IF ANY CHARGES WILL BE ASSESSED.

	STORE	QTY	COST	TOTAL
BARNEYS	RTV		RETURN MERCHANDISE	
	1	-1	0.00	0.00
TOTAL UNITS RA'ED -1				
TOTAL DOLLARS RA'ED 0.00				



