Remington Arms Co., Inc. Product Service Legal Case #:7523

Case Information

RE# **Date Opened Date Closed Incident Date** Date Opened(PS) Pre Lit Lit Obsolete

3/23/2012 262844 3/26/2012 3/26/2012

Customer Information

Type Business First Name Last Name Street City State Zip Contact

5895 Red Fox Run North Branch Incident Harold Bauer MN 55056

Incident Information

Medical Repair Medical Codes Claims Est. Treatment Status

PΙ

PD Cause:4006 Altered Adjustments or Components

Concern: 1025 Unexplained Discharge - No Mention of Unknown Gun has discharged on S

Safety Position occassion

C

4/12/12 Per note on SR, gun has discharged on occassion.cm

Firearm Information

Model/Ga. SKU Mfg. Serial Bbl. DOM Type Remington CF/BA 700/3006 SPRG n/a A6621639 PQ 6/12/1978

Original Owner Where Purchased Date Purchased Accessories

OUTDOOR SPT HQ DAYTON OH BOTTOM HALF SEE THRU MOUNTS U

CONCERN: DISCHARGED ON OCCASION

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Cash Reim. Date Cash Date Release of Claims Settlement Release Date Reimbursement Settlement APV APV

Replace TPA, clean, test at

BLSM

Repair/Replacement Repair/Replacement Cost Date

30.40 4/13/2012

4/12/12 Per Ilion, trigger assm dirty and set screws altered. Replace TPA, clean, test at BLSM.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		3/26/2012
Examination	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4006	Altered Adjustments or Components	
	Description		22" 3006 SPRG
	Date Code		PQ
n1	Bore Plugged	False	
Barrel	Bulged	False	
	Fired	False	
	Fired while Obstructed		

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=7523&Type=Case

4/13/2012

	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	-
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Not Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		M/700 BOLT LOCK SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.009
Sear	Notch	Slightly Worn; Functioning	
	T	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	DIRTY AND TRIG NOT RETURNING WILL FOLLOW DOWN
	Pull	Select	2.5#
	Altered	Truc	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		BOTTOM HALF SEE THRU MOUNTS

Service Request

Remington Service PO Box 700



Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT ,00°

SR00015357

WITH YOUR RETURN.

Serial Number / Description Number

A6621639

HAROLD BAUER 5895 RE FOX RUN

NORTH BRANCH, MN 55056 US

Email:

Date of Request: 03/16/2012 Date Printed: 03/16/2012

Destination: Arms Services 14 Hoefler Ave Ilion, NY 13357 US

Your request for service on the item(s) will be evaluated by our repairman. You will be contacted with an estimate before work is performed.

M238 - CLEAN & INSPECT (SAFETY PROGRAM ONLY)

M240 - BOLT LOCK SAFETY MODIFICATION

SMP - guns has discharged on occasion

Parts And Servio Material	te Details - Se Type	Description	Qty Veeded	Warranty	Price	Disc	Amount
4000104	S	ARMS SERV PARTS SHIPPING & HANDLING	12	Billable	1.00	Ò	12.00
4000116	S	GR-LABOR	25 .	Billable	1.00	0	25.00

A6621639

T.A. Linky & Set Screws A Hered.

Alpha TOA, cleart rest under

Rip Coz & 20 +

anste

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) being sent based on the conversation with our representative.

Sub Total:

37.00 .00

Est Sales Tax:

Grand Total:

\$37.00





