

Remington Arms Co., Inc.
Product Service
Legal Case #:8319

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
291886	12/7/2012	12/11/2012	12/11/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Walter	Beard	175 Archers Place	Madison Heights	VA	24572		H 434-384-2327 E wrb3728@gmail.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern		Unknown	
S FBC	Concern:1008 Fired on Bolt Closing			
C				

SR# 35668 - Notes on Repair: Per consumer email - Has a 308 bdl; loaned it to a friend who was target shooting.he loaded it and it fired by itself twice.....This gun has never been modified. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/308 WIN	n/a	A6743947	OY	7/1/1974
Date Purchased	Where Purchased	Accessories	Original Owner			
	SANDY DIST CHARLESTON WV		U			

CONCERN: FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Quote to repair under BLM						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$29					

12/13/12: Per Ilion - Could not duplicate concern. TA has an excess amount of lube. Replace TA, clean & test under BLM - quote. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		12/11/2012
	Product Type		RF
	Action Type		A
	Assigned To		J.BALIO
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 308 WIN
	Date Code		OY
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	

Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	.012
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Functioning	HAS AN EXCESSIVE AMOUNT OF LUBE.
	Pull	---Select---	4.5#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	

frmREInquiry - Repair Inquiry

Repair Number: RE00291886 Serial: A6743947 Model 700 Center Fire Caliber: 308 Repairman: WIN
 Verify Repair High Priority Status: New 11/20/2012 10:06:29 AM

ADDRESS INFORMATION

Customer ☒ Received from **Return To** ☐ Received from
 Name: WALTER BEARD WALTER BEARD
 Address 1: 175 ARCHERS PLACE 175 ARCHERS PLACE
 Address 2: PO Box: PO Box:
 City: MADISON HEIGHTS MADISON HEIGHTS
 State: VA Zip Code: 24572 Country: US VA Zip Code: 24572 Country: US

FFL: 01011900

Contact / Condition Problems Estimate History / Status Shipping / Billing

Contact Information

Phone: 434 384 2327
 Fax:
 Email: wrb3728@gmail.com
 Comments: FBC

Received Condition

Good
 Condition Notes
 CSR Notes: a 308 bdl; loaned it to a friend who was target shooting.he loaded it and it fired by itself

Accessories Received

Code	Desc	Qty
A007	With Stud	2

could not dup concept
 T.A. WAS AN EXCESS AMT. OF
 lube. lube. TPA, 26 ANS TEST
 und. BLP for 10. + Q

Refresh

Close

Serial Number:

A6743947 SHIPPED DEC 18 PAID

Model: 700



RE00291886

Tuesday, Dec 11 2012 4:04 AM

Tuesday, Dec 11 2012

4:04 AM





