

Remington Arms Co., Inc.
Product Service
Legal Case #:7454

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
260463	2/29/2012	3/1/2012	3/1/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Carlyle	Beecher	2391 Darrell Dr	Fitchburg	WI	53711		H 608-271-8323 C 608-669-8323

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4015 Improper Maintenance		Unknown	
S Safety not working	Concern:1032 Safety not working properly			
C				

3/12/12 Per letter with rifle, the safety will not work and the trigger will not work. A couple of times it has gone off on it's own. He has had the gun since new and never had a trigger job. He took it out of the stock per one of our Tech's advice, to try and see if anything obvious was wrong with it. He didn't really see anything and put it back in the stock.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/300 SAUM	26436	S6464995	LX	2/12/2003 4:49:39 PM
Date Purchased	Where Purchased	Accessories	Original Owner			
	ACUSPORT (OH) CORPORATION		U			

CONCERN:GONE OFF ON IT'S OWN

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, can offer to replace TPA, clean and test at 1/2 normal cost						

Repair/Replacement Cost	Repair/Replacement Date

3/12/12 Per Ilion, trigger assm has a dried lube residue causing parts to bind. Sear and bolt stop are binding. Can offer to replace TPA, clean and test at 1/2 normal cost.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		3/1/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4015	Improper Maintenance	
Barrel	Description		24" 300 SAUM SS
	Date Code		LX
	Bore Plugged	False	
	Bulged	False	
	Fired	False	

	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	--Select--	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	--Select--	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	--Select--	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	ISS	
Sear	Lift	--Select--	.013
	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	HAS A DRIED LUBE RESIDUE SEAR AND BOLT STOP BINDING
	Pull	--Select--	10+#
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	

7454

24"
Lx2/03
10+
1013

Serial
Number:

S6464995

Model: 700



RE00260463

T.A. has a dried lube residue
causing parts to bind. Sear +
Bolt stop and BINDING. can offer
to up here TPA, clean + test AT
1/2 normal cost.

@ note

RECEIVED
MAR 02 2012
BY: _____

Something is wrong with my gun.
The safety will not work. And the
trigger will not work. A couple of
times it has gone off on its own!!!
I have had the gun seience new.
The gun has never had a trigger job.
I took it out of the stock (per one of
your techs advice) to try & see if anything
obvious was wrong with it. I didn't
see anything and put it back in the
stock. I have have owned many 700
Rem. and never had a problem with
any of them. I assume this will be
under warranty. Please call with
any questions.

Thanks

Carlyle Beecher

Carlyle Beecher

2391 Darrell Dr.

Fitchburg, WI

53711

Phone Cell - 608-669-8323 *

Home - 608-271-8323





