

Remington Arms Co., Inc.
Product Service
Legal Case #:7550

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
263520	3/30/2012	4/2/2012	4/2/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter		John	Boardman	13 Tilley Ave.	Pompton Plains	NJ	07444		H n/a

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern		Unknown	
S FSR	Concern:1007 Fired on Safe Release			
C				

Customer sent rifle in w/note. He asked that we check the safety fo this gun. He said that he did not know if anyone had ever adjusted the trigger. He stated the last time he used it he had a FSR. No reported damage or injury. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial Bbl.	DOM
Remington	CF/BA	700/308 WIN	n/a	6883713 OZ	7/8/1975
Date Purchased	Where Purchased	Accessories	Original Owner		
	NATIONWIDE SPTS SOUTHAMPTON PA	SCOPE BASE,RINGS,SLING	U		

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Quote to repair under BLM						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$30					

4/9/12: Per Ilion - Could not duplicate concern. TA set screws altered. Replace TA, clean & test fire under BLM - quote. Customer paid quote. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		4/2/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 308 WIN
	Date Code		OZ
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Not Functioning	BINDS
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.010
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	HEAVY TRIG PULL
	Pull	---Select---	7#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		SCOPE BASE,RINGS,SLING

22"
027/75
7#
010

7550

DEAR SIR

I am sending you my Remington 700-308
To have you check the safety of this gun
I don't know if anybody has ever adjusted
The Trigger. I have used use this gun for
many years but I remember the last time
I use it when I push off the safety the
gun went off. Please take care of
this for me. You can call me at
973-897-2259 call too let me know
on cost & payment.

Please when done ship to
T & T Custom Metal
85 Fifth Ave
PATERSON, N.J.

07524

My name & address -
JOHN BOARDMAN
13 Tihley Ave
Pompton Plains N.J.

07747

could not duplicate concern.

T.A. set screws altered. replace
TPA, clean rest when RCP
COR 820.1

RECEIVED
APR 09 2012

BY:

Serial
Number:

6883713

Model: 700



RE00263520





