

Remington Arms Co., Inc.
Product Service
Legal Case #:7579

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
264582	4/11/2012	4/12/2012	4/12/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Raymond	Brininger	1545 A St	Butte	MT	59701		H 406-782-5432

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4006 Altered Adjustments or Components		Unknown	
S	Fired on safety release Concern:1007 Fired on Safe Release			
C				

5/7/12 Per note with rifle, Raymond has not used this rifle in a couple of years and his 14 yr old grandson would like to have it. Raymond decided to check this rifle out after reading some stories and found that it would fire when releasing the safety without squeezing the trigger.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/7MM REM MA	n/a	336693	AR	3/1/1968
Date Purchased	Where Purchased	Accessories	Original Owner			
		SCOPE BASE,SLING,AFT MKT STK	U			

CONCERN: FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Replace TPA, clean, test at BLSM program price						
	Repair/Replacement Cost	Repair/Replacement Date				
	30.40	5/7/2012				

5/7/12 Per Ilion, trigger assm very dirty, set screws altered, trigger not returning. Replace TPA, clean, test at BLSM program price.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		4/12/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4006	Altered Adjustments or Components	IMPROPER MAINTENENCE
Barrel	Description		24" 7MM REM MAG SS MUZZLE BRAKE
	Date Code		AR
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while		

	Obstructed		
	Muzzle/Crown Condition	Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	SLUGGISH
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	---Select---	AFT MKT
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.007
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	DIRTY,SOME RUSTING,TRIG IS NOT RETURNING WILL FOLLOW DOWN
	Pull	---Select---	5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		SCOPE BASE,SLING,AFT MKT STK

7579

24"
AR23/68
5#
.007

Sirs.

I bought this old gun
in 1971 and I never had
a problem with it. I quit
hunting 2 years ago (Am 75)
and recently my 14 year old
Grandson said he would
like to have the gun. I have
read some stories about
problems with this model
so I decided to check it
so it would be safe for
him and it would fire
when releasing the safety
without squeezing the trigger.
I would like to fix it
before I give it to him.

Thank you

RAYMOND BRININGER
1545 A ST
BUTTE, MT 59701
406-782-5432

Serial
Number:

336693

Model: 700



RE00264582

T.A. very dirty, set screws A Hered.
TRIG. not returning. replace
TPA, clean & test under BCP for
\$20. +

RECEIVED
APR 16 2012

Quote

BY:.....







