Obsolete

C 318-715-9009

Remington Arms Co., Inc. **Product Service** Legal Case #:7732

**Date Closed** 

**Incident Date** 

Pre Lit

Lit

Case Information

**Date Opened** 

RE#

\_ 7/11/2012 274072 6/15/2012 \_ 7/16/2012 Customer Information Last Name Business First Name City State Contact Type Street Zip Age H 318-336-9009 4899 Hwy 84 West Incident Brian's Marine Doyle Bryan Vidalia LA 71373

Incident Information

Repair Est. Medical Treatment Medical Status Claims Codes

PI.

PD Cause:4038 Could Not Duplicate Concern Unknown S Fired when releasing the safety Concern:1007 Fired on Safe Release

Date Opened(PS)

6/15/12 Per call from Doyle, his wife has had two incidents of her 700 youth 7mm-08 Model 700 firing when she released the safety. Once about 5 years ago and then again last year.cm

Firearm Information

Model/Ga. SKU DOM Mfg. Serial Rhl. Type 700/7MM-08 REM 5/8/2002 7:47:06 AM CF/BA 27453 G6247128 KW Remington **Date Purchased** Where Purchased Accessories **Original Owner** SPORTS SOUTH INC Y

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Cash Reim. Date Cash Date Settlement Release of Claims Release Date Reimbursement Settlement APV

Per Ilion, replace TPA, clean, test at 1/2 normal cost

Repair/Replacement Repair/Replacement Cost Date

6/15/12 Mailing box and ARS.cm 7/19/12 Per Ilion, could not duplicate concern. Trigger assm very dirty and sticky. Replace TPA, clean, test at 1/2 normal cost.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		7/16/2012
Examination	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	IMPROPER MAINTENANCE
Barrel	Description		20" 7MM-08 REM
	Date Code		KW
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=7732&Type=Case

7/19/2012

	-1 <u></u>		<del></del>
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Not Functioning	BINDS
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	Select	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
Overall	Exterior Condition	Slightly Worn; Functioning	DIRTY,RUSTY
	Stock Condition	Slightly Worn; Functioning	DIRTY
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Received	Bulged	False	
Safety	Description		M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	ISS	
Sear	Lift	Select	.016
	Notch	Slightly Worn; Functioning	DIRTY
		Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Functioning	VERY DIRTY AND STICKY
	Pull	Select	4.5#
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	



#### Remington Service PO Box 700

Madison, NC 27025-0700



arts and Repairs: P:800-243-9700/F:336-548-7801

document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. Fixed Concerns and provide you with accurate and complete service. serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT

ما10.

vice Request Number

TH YOUR RETURN.

Serial Number / Description

00022260

G6247128

Model 700 RIFLE

stomer: **DOYLE BRYAN** 

**BRIAN'S MARINE** 4899 HWY 84 WEST VIDALIA, LA 71373 US

Email: Christy

Date of Request: Date Printed: 06/15/2012

06/15/2012

Destination:

Arms Services 14 Hoefler Ave Ilion, NY 13357 US

Email:

ur request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and irned. If not, you will be contacted with an estimate before work is performed.

ason For Return

- FORWARD TO PRODUCT SERVICE FOR INSPECTION

rvice Request Section

red on 2 occassions when releasing the safety.

rts And Service Details 🥰

Description

Needed

arranty

5% GP341198 model -

G6247128

Model:

700

could not deplicate concerne T-A. Very dinty + Sticky.

Riphace TPA, CheAnt Test AT

1/2 MONANI COST.

1 9 2012

Sub Total:

.00

Est Sales Tax:

.00

IS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) ng sent based on the conversation with our representative.

### ARS LABEL REQUEST FORM

DATE:	06/15/2012	Service Request #	SR00022260
QUANTITY:	1	WEIGHT PER PACKAGE:	10 LBS
	mitchelles	email address:	Christy.Mitchell@remington.com
		, · .	

**Business:** 

Remington Service PO Box 700 Madison, NC 27025-0700 www.Remington.com

#### LABEL INFORMATION

MAIL LABEL TO:

DOYLE BRYAN BRIAN'S MARINE 4899 HWY 84 WEST SR00022260 VIDALIA, LA 71373 US Email: Christy

**RETURN ITEM TO:** 

ILN

Arms Services . .

4XX596 JUN 15, 2012 ACT WT 10.0 LBS #PK 1 SVC GNDCOM BL WT 10.0 LBS TRACKING# 1Z4XX5969066121125 ALL CURRENCY USD REF 1:SR00022260 REF 2:

ATTN: Prod Serv #7732

## **#Pitney Bowes**



# ShipRequest™



Ship To:

Doyle Bryan

Company:

Bryan's Marine

Address 1:

4899 Hwy 84 West

Address 2:

Address 3:

City:

Vidalia

State/Province:

Louisiana

ZIP/Postal Code: 71373

Country:

United States

email:

Phone:

Account:

230145

Package Type:

Package

Address Type:

Residential

Deliver By:

Fri, June 22, 2012

Package ID:

8800

Special Instructions:

Sender Name:

Christy Mitchell

email:

Christy.Mitchell@remington.com

Prepared By:

Phone:

Total \$







