Remington Arms Co., Inc. Product Service Legal Case #:7086

Case Information

**Incident Date** Obsolete RE# **Date Opened** Date Opened(PS) **Date Closed** Pre Lit Lit 12/14/2011 1/5/2012 252493 1/4/2012

Customer Information

First Name Last Name Street Contact Type Business City State Zip Age Reporter Bullets & Bows 110 W. Louisiana Ave. Raine LA W 337-334-0033 **Bullets & Bows** 70578 Kenny

Incident Information

**Medical Status** Repair Est. Claims Codes Medical Treatment

PΙ

PD Cause:4038 Could Not Duplicate Concern S Concern: 1007 Fired on Safe Release

Unknown

C FSR

12/14/11: Dealer called in. He stated a consumer brought him the gun & said he had a FSR with it. No report of injury or damage. df

Firearm Information

Mfg. Model/Ga. SKU Serial Bbl. DOM Type Remington CF/BA 700/7MM REM MA 27480 E6842148 WP 8/11/1995

Where Purchased

Accessories TWO PIECE BASE

Original Owner

Date Purchased

WAL MART WAREHOUSE 3R

U

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Reim. Date Cash Date Release of Claims Release Date Settlement Reimbursement Settlement APV APV

Per Ilion - Quote to repair

> Repair/Replacement Repair/Replacement Cost Date

12/15/11: Mailing ARS & forms. df 1/4/12: Per Ilion - Could not duplicate concern. TA very dirty. Can offer to replace TA, clean & test fire @ 1/2 normal cost - quote. df


Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/5/2012
	Product Type		RF
	Action Type		Α .
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		24" 7MM REM MAG
	Date Code		WP
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	·
	Firing Pin	Slightly Worn; Functioning	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=7086&Type=Case

1/23/2012

1 .			
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
<u> </u>	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	•
Receiver	Condition	Slightly Worn; Functioning	·
Receiver	Bulged	False	
	Description		M/700 SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.013
Sear	Notch	Slightly Worn, Functioning	
	T4-	Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Functioning	VERY DIRTY
· ·	Pull	Select	5.5#
Trigger	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	•
Non-Remington Components	Description		TWO PIECE BASE



2086

December 14, 2011

Bullets & Bows Attn: Kenny

110 W. Louisiana Ave. Raine, LA 70578 Phone: 337-334-0033

Ref: #7086, Model 700, Serial # E6842148

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination and service request.

Please include a copy of this letter and service request to put inside the shipping container. The letter and service request inside are important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results. I will contact you once I get the report.

I hope this action will keep you a loyal Remington customer.

Sincerely,
Dell Fulcher
Consumer Affairs Administrator
Remington Arms Co., LLC

Phone: 1-800-243-9700 press 0 and ask for ext 8686

Fax: 336-548-7872

E6842148

Model: 700

RE00252493

to up how TDA, chem stest One at 1/2 Normal cost

Remington Arms Company, LLC • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

## Service Request

## Remington Service PO Box 700

12/15/2011

12/15/2011

Date of Request:

Printed:

Date

Madison, NC 27025-0700

ATTN: Product Service

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service.PLEASE RETAIN THIS COPY FOR YOUR RECORDS.

Service Request Number Serial Number / Description

SR00006750

E6842148

Model 700 Center Fire

**Customer:** 

BULLETS & BOWS ATTN: KENNY 110 W. LOUISIANA AVE.

RAINE, LA 70578 US

Destination:

Arms Services 14 Hoefler Ave Ilion, NY 13357 US

Email:

Email:

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return

M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION

Service Request Section

Product Service # 7086 - FSR

Parts And Service Details

Material

Type

Description

Qty Needed

Warranty

Price

Disc Amount

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) being sent based on the conversation with our representative.

Sub Total:

.00

Est Sales Tax:

.00

Print	Reset
-------	-------

Model Number: 200	Alumban - 10 1/2/47			
Are you the original owner?:     YES   NO				
Name:	Date of Purchase:			
Address (no PO Boxes):				
City:	State:	Zip:		
Phone (Daytime):	Fax:			
E-mail Address:(if e-mail address is provided, notification of receipt and shipment will be sent)				
E-mail Ac		om Remington.		
Please describe your proble	m and date of			
		· · · · · · · · · · · · · · · · · · ·		
· ·				
	•	:		
		:		
500 <b>ch</b> a	racters left	<u> </u>		
Ammunition I	nformation:			
Manufacturer:	Type:			
Other (i.e. bullet weight/type, shot size, powder):				
Handload Information:				
Powder Used:	Powder We	(2) 20 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2		
Case/Hull Used:	Primer Us	ed:		
Bullet Type/Shot Size:	Reloader L	Ised:		
Firearms Care (Cleaning and Lubrication):				

http://www.remington.com/asp/factory\_repair\_form.asp

8/25/2011

Brand of cleaning solution used:
How often do you clean the bore? (Months or Number of rounds)
How often do you clean the action? (Months or Number of rounds)
How often do you clean the trigger assembly? (Months or Number of rounds)
Brand of lubricant used:
How often do you lubricate the bore? (Months or Number of rounds)
How often do you lubricate the action? (Months or Number of rounds)
How often do you lubricate the trigger assembly? (Months or Number of rounds)
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? >□ YES □ NO
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?)
What were the services performed?)
Ship your INSURED firearm by either UPS or Parcel Post to:
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357
□ WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM. :: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling.
Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper

http://www.remington.com/asp/factory\_repair\_form.asp

8/25/2011

return address will be refused.

:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for

damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)

:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.

## ARS LABEL REQUEST FORM

DATE:	12/15/2011	Service Request #	SR00006750
QUANTITY:	1	WEIGHT PER PACKAGE:	10 LBS
REQUESTED BY:	fulcherdm	email address:	I WILL MAIL LABEL

**Business:** 

Remington Service PO Box 700 Madison, NC 27025-0700

www.Remington.com

## LABEL INFORMATION

**MAIL LABEL TO:** 

**BULLETS & BOWS** ATTN: KENNY 110 W. LOUISIANA AVE. SR00006750 RAINE, LA 70578 US Email:

**RETURN ITEM TO:** 

ILN

Arms Services



TTN: Product Service

4XX596 DEC 15, 2011 ACT WT 10.0 LBS #PK 1 SVC GNDCOM BL WT 10.0 LBS #PK 1 TRACKING# 124XX5989086834149 ALL CURRENCY US ALL CURRENCY USD REF 1:SR00006750 REF 2:

FRT: 3RD HANDLING CHARGE 0.00 SVC T/P USD SHIPMENT PUB RATE CHARGES: COD 0.00 DGD 0.00 RS 0.50 00.0 VO 0.00 DGD DC 0.00 ROD 0.00 PR AH 0.00 TOT PUB CHG 10.27 PUB+HANDLING 10.27

