

Remington Arms Co., Inc.
Product Service
Legal Case #:8239

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
290583	11/28/2012	11/30/2012	11/30/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Andrew	Campbell	602 Freeman St	Clymer	NY	14724		H 716-459-7941 E drewand5104@yahoo.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4006 Altered Adjustments or Components		Unknown	
S	Fired when moving safety Concern:1032 Safety not working properly			
C				

12/19/12 Per note on SR, gun misfire, take gun off safe and the gun fired. Happened 3 yrs ago. He took to Gander Mtn and the gunsmith said he fixed the problem. Did it again 11/17/12.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPRG	n/a	A6346853	WI	8/27/1976
Date Purchased	Where Purchased	Accessories	Original Owner			
	H L PETERS BUFFALO NY	TWO PIECE BASE	U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, repair TPA, clean, test at no charge per M. Johnson						
	Repair/Replacement Cost	Repair/Replacement Date				

12/19/12 Per Ilion, trigger assm set screws altered. Trigger not returning properly. Repair TPA, clean, test at BLSM program price.cm
12/19/12 M. Johnson having repaired at no charge.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		11/30/2012
	Product Type		RF
	Action Type		A
	Assigned To		J.BALIO
Cause	4006	Altered Adjustments or Components	
Barrel	Description		22" 3006 SPRG
	Date Code		WI
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	METAL FINISH WORN,RUSTY
	Stock Condition	Slightly Worn; Functioning	MARS SCRATCHES
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.009
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	TRIG NOT RETURNING PROPERLY WILL FOLLOW DOWN
	Pull	---Select---	3#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

frmRepairMain - FGI Repairs

File Add Repair Estimate Repair Expedite Repair Inquiry Repair Tools CSR Tools Reports Table Maintenance System

frmREInquiry - Repair Inquiry

Repair Number: RE00290583

Serial: A6346853 Model 700 Center Fire Caliber: 30-06 Produced: 08/27/1976 SKU: 20000

Repairman:

Verify Repair

High Priority

8239

ADDRESS INFORMATION

Customer

Received from

Name: ANDREW CAMPBELL

Address 1: 602 FREEMAN STREET

Address 2: PO Box:

City: CLYMER

State: NY Zip Code: 14724 Country: US

FFL: ☐

Contact / Condition Problems Estimate History / Status Shipping / Billing

Contact Information

Phone: 716 459 7941

Fax:

Email: drewand5104@yahoo.com

Comments:

Received Condition

Good

Condition Notes

CSR Notes:

gun fired when moving safety. Consumer would like to be contacted after gun is evaluated.

Code	Desc	Qty
A007	With Stud	2
A016	Scope Base	2

Refresh

Close

T.A. set screws altered.
 T119, not set properly.
 Mr. TPA clear to Sturden
 BCP Ron & 20. & 20.

Remington model 700 30-06
 Serial# - A6346853

Gun misfire - Take gun
 off safe and Gun Fired.

Happened 3yrs ago took to Gander mtn
 Gunsmith "said fixed Proble" Did it again 11/17/12

Serial Number:

A6346853

Model: 700



RE00290583

DEC 03 2012

Friday, Nov 30 2012 ILASPR11

3:40 AM

Friday, Nov 30 2012 BY: 3:40 AM





