Remington Arms Co., Inc. Product Service Legal Case #:7257

				Product Service	,					
Case Inform	ation			Legal Case #:7257	,					
RE#	Date Opened	Dat	e Opened(PS)	Date Close	d Incident Date		Date	Pre Lit	t Lit	Obsolete
253347 1/10/2012			1/11/2012	1/11/2012						
Customer In	formation									
Туре	Business	First Name	Last Name	Street	City	State	Zip	Age	Сог	ıtact
Reporter	Chatsworth Sptg Goods		Chatsworth Sptg	300 South 3rd Ave	Chatsworth	GA	30705	chatsw		E vn@yahoo.com
ncident Info	ormation									
(Claims		Co	des	Rej	pair E	st. M	ledical Treati	ment :	Medical Status
ΡI										
PD	•	Cause:400	6 Altered Ad	ljustments or Compo	nents			Unknown		
S Fires when closing bolt C		Concern:1	Cilkilowii							
/26/12 Per	note on SR, when	closing the bo	lt the gun fires.	.cm						
irearm Info				•						
Mfg.		Туре		Model/Ga.	SKU			Serial	Bbl.	DOM
	ngton	CF/BA		700/280 REM		25857		D6221299	OP	7/21/1995
Date Pu	ırchased	Where Purchased FABER BROS INC		Accessories	Original Owner U					
ONCERN:		I ADLK BRO	3 INC		U					
Other Produ- Settlement	cts Information - I	None Defined		Remington/700/CF/E	3A					
s	Settlement	Releas	se of Claims	Release Date	Reimb	ursen	ent			Date Cash Date
	place TPA, clean, 1/2 normal cost	test					i	Settlement	APV	APV
inc at	1/2 norman cost	Repair	Replacement Cost	Repair/Replacem Date	ent					
/26/12 Per l		dirty and rust	y, set screws al	tered. Trigger binds a	and not retur	ning p	roperly	y. Replace TP	A, clear	n, test fire at 1/2
				~~··						
xamination	I[Remington/CF/E									
Part	Sub-Pa	art	(Code				Comment		
	Examiner				B.TRAVIS					
	Exam Date				1/11/2012					
xamination	n Product Type				RF					
	Action Type				Α					
	Assigned To				T.NAGLE					
Cause	4006	A	ltered Adjustme	ents or Components	IMPROPE	R MA	INTE	VENCE		
	Description				22" 280 RE	EM				
	Date Code				OP					
	Bore Plugged	F	alse]					-
Barrel	Bulged	F	alse]					
	Fired	F	alse		1					

http://cns03an13:200/nsaann/PrintDisnlav asnx?ID=7257&Tvne=Case

Fired while Obstructed

1/26/2012

	Muzzle/Crown Condition	Slightly Worn; Functioning	_	1
Bolt	Firing Pin	Slightly Worn; Functioning		_
	Shroud	Slightly Worn; Functioning		$\left(\cdot \right)$
	Face	Slightly Worn; Functioning		
	Handle	Slightly Worn; Functioning		ļ
	Stop	Slightly Worn; Functioning		
Extractor	Condition	Slightly Worn; Functioning		İ
	Cut Condition	Slightly Worn; Functioning		ŀ
	Ext/Eject Test	False		ì
Locking	Block Condition	Select		
	Lug Condition	Slightly Worn; Functioning		E
	Notch Condition	Select		
	Condition	Select		
Magazine	Box Condition	Slightly Worn; Functioning		
Overall	Exterior Condition	Slightly Worn; Functioning		
	Stock Condition	Worn; Functioning	MARS,SCRATCHES FINISH WEAR	
	Fore End Condition	Select		
Receiver	Condition	Slightly Worn; Functioning	<u> </u>	
	Bulged	False		
Safety	Description]	M/700 SAFETY	
	Function	Like new; Functioning		
	Sub-Assembly	Non-ISS		
Sear	Lift	Select	.014	
	Notch	Slightly Worn; Functioning		
	Tests	Test Fired	False .	
Feeding Test	16363	False		
Trigger	Condition	Slightly Worn; Not Functioning	DIRTY, RUSTY.TRIG BINDS WILL FOLLOW DOWN	1 (丿
	Pull	Select	4.5#	
	Altered	True	SET SCREWS ALTERED	
	Sub-Assembly	M/700 Non-Bolt Lock	<u></u>	

Service Request

Remington Service



Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700/F:336-548-7801 www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. To serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service PLEASE RETAIN THIS YOUR RECORDS.

Service Request Number / Description

SR00008162

D6221299

Model 700 RIFLE Caliber: 280

Customer: CHATSWORTH SPORTING GOODS 300 SOUTH 3RD AVE CHATSWORTH, GA 30705 US

Email: chatsworthpawn@yahoo.com

Date of Request01/03/2012 Printed01/03/2012

Destination: Arms Services 14 Hoefler Ave Ilion, NY 13357 US

Email

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be rep. returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return M994 - BOLT

Service Request Section When closing the bolt the gun fires

Parts And Service Details

Description

Qtv Needed

Price Disc Amount

T.A. dipty a rusty, set screws Altered. Trig BINDS & NOT Returning properly. Replace TPA, LleAN - Test fishe AT 1/2 NODWAL COST

Sub Total: Est Sales Tax: .00 .00

Grand Total:

\$.00





