

Remington Arms Co., Inc.
Product Service
Legal Case #:7584

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
264815	4/13/2012	4/16/2012	4/16/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Andres	Chavez Jr.	694 La Mesa St.	Rio Grande City	TX	78582		H 956-353-9566 F 956-735-9809

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4015 Improper Maintenance		Unknown	
S FSR	Concern:1007 Fired on Safe Release			
C				

Customer sent rifle in w/note. He stated the rifle fired when taking the safety off. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/2506 REM	n/a	6332387	AP	3/1/1967
Date Purchased	Where Purchased	Accessories	Original Owner			
	CASSO GUERRA LAREDO TEX	TWO PIECE BASE	U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Quote to repair under BLM						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$29					

4/19/12: Per Ilion - TA very dirty & rusty, parts binding/working sluggish. Replace TA, clean & test fire under BLM - quote. df 4/24/12: Customer apprvd & paid quote. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		4/16/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4015	Improper Maintenance	
Barrel	Description		24" 2506 REM
	Date Code		AP
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown		

	Condition	Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	BOLT VERY DIRTY AND BINDS IN REC
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Not Functioning	BINDS
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	--Select--	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Worn; Functioning	DIRTY,RUSTY
	Stock Condition	Worn; Functioning	MARS,SCRATCHES
	Fore End Condition	---Select---	
Receiver	Condition	Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Slightly Worn; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.010
	Notch	Slightly Worn; Functioning	DIRTY
	Tests	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Functioning	VERY DIRTY,RUSTY PARTS WORK SLUGGISH/BIND
	Pull	---Select---	3.5#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

Andres Chavez Jr.
6941 La Mesa St.
7584 - Rio Grande City, TX 78582
(950) 353-9566
(950) 735-9809

Remington model 700
(recall) bolt lock.
when taking off the
safe, it fires by itself.

24"

APR 3/07

315#

.010"

5332387

Model: 700



RE00264815

RECEIVED
APR 19 2012

BY:

T.A. very dirty & rusty parts
BINDING/WORKING SLUGGISH.
Replace TPA, clean best under
BCP for BDO.

Quote







