

Remington Arms Co., Inc.
Product Service
Legal Case #:8396

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
293798	12/20/2012	12/21/2012	12/21/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Roy	Cochran	4509 McGehan Rd	Desoto	MO	63020		H 636-232-8964 E roy.cochran69@gmail.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern			Unknown
S	Fired when safety was disengaged Concern:1007 Fired on Safe Release			
C				

1/8/13 Per note on SR, accidental discharge when safety was disengaged.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPRG	n/a	A6204733	DZ	9/23/1975
Date Purchased	Where Purchased	Accessories	Original Owner			
	S&T IND LOUISVILLE KY	TWO PIECE BASE	U			

CONCERN: FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean and test at BLSM program price						
	Repair/Replacement Cost	Repair/Replacement Date				
	29.04	1/8/2013				

1/8/13 Per Ilion, could not duplicate concern. Trigger assm dirty, rusty. Replace TPA, clean and test at BLSM program price.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		12/21/2012
	Product Type		RF
	Action Type		A
	Assigned To		J.BALIO
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 3006 SPRG
	Date Code		DZ
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	

Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	010
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY,RUSTY
	Pull	---Select---	6#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

frmREInquiry - Repair Inquiry

Repair Number: **RE00293798**

Serial: A6204733 Model 700 Center Fire Caliber:
3006 SPRG Produced: 09/23/1975 SKU: 20000

Repairman:

Verify Repair

Status: New 11/26/2012 12:54:12 PM

8396

ADDRESS INFORMATION

Customer

☒ Received from

Return To

☐ Received from

Name: ROY COCHRAN

ROY COCHRAN

Address 1: 4509 MCGEHAN RD

4509 MCGEHAN RD

Address 2: PO Box:

PO Box:

City: DESOTO

DESOTO

State: MO Zip Code: 63020 Country: US

MO Zip Code: 63020 Country: US

FFL: 01011900

Contact / Condition Problems Estimate History / Status Shipping / Billing

Contact Information

Phone: 636 232 8964

Fax:

Email: ROY.COCHRAN69@GMAIL.COM

Comments:

Received Condition

Good

Condition Notes

CSR Notes: ACCIDENTAL DISCHARGE
WHEN SAFETY WAS
DISENGAGED

could not find concern
T.A. dirty rusty. Rep
for correct test and
BLP for #40. T &

Accessories Received

Code	Desc	Qty
A007	With Stud	2
A008	With Swivel	2

Refresh

Close

Serial Number:

A6204733

Model: 700

BY:



RE00293798

Friday, Dec 21 2012 11:43 AM

Friday, Dec 21 2012

3:43 AM

22"
DZ 9/75
6#
1010







