

Remington Arms Co., Inc.  
Product Service  
Legal Case #:8356

## Case Information

| RE#    | Date Opened | Date Opened(PS) | Date Closed | Incident Date | Pre Lit | Lit | Obsolete |
|--------|-------------|-----------------|-------------|---------------|---------|-----|----------|
| 292748 | 12/13/2012  | 12/14/2012      | 12/14/2012  |               |         |     |          |

## Customer Information

| Type     | Business          | First Name | Last Name       | Street              | City       | State | Zip   | Age | Contact   |
|----------|-------------------|------------|-----------------|---------------------|------------|-------|-------|-----|---|
| Reporter | Duke's Sport Shop | Duke/Wes   | Duke's Sport Sh | 2801 New Butler Rd. | New Castle | PA    | 16101 |     | W 724-652-6019<br>F 724-652-2538<br>E<br>duke@dukessportshop.comcastbiz.net |

## Incident Information

| Claims | Codes                                  | Repair Est. | Medical Treatment | Medical Status |
|--------|--|-------------|-------------------|----------------|
| PI     |  |             |                   |                |
| PD     | Cause:4038 Could Not Duplicate Concern |             | Unknown           |                |
| S FSR  | Concern:1007 Fired on Safe Release     |             |                   |                |
| C      |  |             |                   |                |

Dealer sent rifle in w/note. Dealer stated the gun will discharge when the safety is released sometimes. df

## Firearm Information

| Mfg.           | Type                         | Model/Ga.     | SKU            | Serial  | Bbl. | DOM       |
|----------------|------------------------------|---------------|----------------|---------|------|-----------|
| Remington      | CF/BA                        | 700/3006 SPRG | n/a            | 6747515 | XY   | 12/1/1974 |
| Date Purchased | Where Purchased              | Accessories   | Original Owner |         |      |           |
|                | L ROHRER GUN STR NW CSTLE PA |               | U              |         |      |           |

CONCERN: FSR

Ammunition Information - None Defined

Other Products Information - None Defined

## Settlement

| Settlement                            | Release of Claims       | Release Date            | Reimbursement | Cash Settlement | Reim. Date APV | Cash Date APV |
|---------------------------------------|-------------------------|-------------------------|---------------|-----------------|----------------|---------------|
| Per Ilion - Quote to repair under BLM |                         |                         |               |                 |                |               |
|                                       | Repair/Replacement Cost | Repair/Replacement Date |               |                 |                |               |
|                                       | \$29                    |                         |               |                 |                |               |

12/19/12: Per Ilion - Could not duplicate concern. Can offer to replace TA, clean & test under BLM - quote. df

## Examination[Remington/CF/BA]

| Part        | Sub-Part     | Code                        | Comment       |
|-------------|--------------|-----------------------------|---------------|
| Examination | Examiner     |                             | B.TRAVIS      |
|             | Exam Date    |                             | 12/14/2012    |
|             | Product Type |                             | RF            |
|             | Action Type  |                             | A             |
|             | Assigned To  |                             | J.BALIO       |
| Cause       | 4038         | Could Not Duplicate Concern |               |
| Barrel      | Description  |                             | 22" 3006 SPRG |
|             | Date Code    |                             | XY            |
|             | Bore Plugged | False                       |               |
|             | Bulged       | False                       |               |
|             | Fired        | False                       |               |

|              |                        |                            |                  |
|--------------|------------------------|----------------------------|------------------|
|              | Fired while Obstructed |                            |                  |
|              | Muzzle/Crown Condition | Slightly Worn; Functioning |                  |
| Bolt         | Firing Pin             | Slightly Worn; Functioning |                  |
|              | Shroud                 | Slightly Worn; Functioning |                  |
|              | Face                   | Slightly Worn; Functioning |                  |
|              | Handle                 | Slightly Worn; Functioning |                  |
|              | Stop                   | Slightly Worn; Functioning |                  |
|              |                        |                            |                  |
| Extractor    | Condition              | Slightly Worn; Functioning |                  |
|              | Cut Condition          | Slightly Worn; Functioning |                  |
|              | Ext/Eject Test         | False                      |                  |
| Locking      | Block Condition        | ---Select---               |                  |
|              | Lug Condition          | Slightly Worn; Functioning |                  |
|              | Notch Condition        | ---Select---               |                  |
| Overall      | Exterior Condition     | Slightly Worn; Functioning |                  |
|              | Stock Condition        | Slightly Worn; Functioning |                  |
|              | Fore End Condition     | ---Select---               |                  |
| Receiver     | Condition              | Slightly Worn; Functioning |                  |
|              | Bulged                 | False                      |                  |
| Safety       | Description            |                            | BOLT LOCK SAFETY |
|              | Function               | Like new; Functioning      |                  |
| Sear         | Lift                   | ---Select---               | .007             |
|              | Notch                  | Slightly Worn; Functioning |                  |
|              |                        |                            |                  |
|              | Tests                  | Test Fired                 | False            |
| Feeding Test |                        | False                      |                  |
| Trigger      | Condition              | Slightly Worn; Functioning |                  |
|              | Pull                   | ---Select---               | 4.5#             |
|              | Altered                | False                      |                  |
|              | Sub-Assembly           | M/700 Bolt Lock            |                  |

8356

72"  
x 12/74  
4.5#  
007

Remington Arms Co. Inc.  
Arms Service  
14 Hoefler Ave.  
Ilion, NY 13357

December 5, 2012

To Whom It May Concern:

We are returning a Remington Model 700 BDL 30.06 ser# 6747515 for warranty repair. The gun will discharge when the safety is released sometimes.

As our and your customer is doing without the pleasure of using your product we would like prompt attention to this matter and returned to the address below.

Sincerely,  
Duke Morosky  
Wes Morosky  
Duke's Sport Shop, Inc.  
2801 New Butler Rd.  
New Castle, PA 16101  
Phone: 724-652-6019  
Fax: 724-652-2538  
Email: duke@dukessportshop.comcastbiz.net  
Sports Inc. #743

RECEIVED  
DEC 19 2012

BY:.....

could not dup concern  
can offer to rep. TCA  
clean + test and. BLP  
for 20. + Q

Number: 6747515

Model: 700



RE00292748





