Remington Arms Co., Inc.
Product Service
Legal Case #:8091

Case Information

 RE#
 Date Opened
 Date Opened(PS)
 Date Closed
 Incident Date
 Pre Lit
 Lit
 Obsolete

 289893
 11/20/2012
 10/26/2012
 11/27/2012
 10/25/2012

Customer Information

Type Business First Name Last Name Street City State Zip Age Contact

Incident Cory Fisher 2898 Grand Prairie Hwy Washington LA 70589 H337-826-5396
C337-945-7392*

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

ΡI

PD Cause:4006 Altered Adjustments or Components

Unknown

S FSR & FBC Concern:1007 Fired on Safe Release

C

10/26/12: Customer called in. He stated he was using rifle on 10/25/12 & had a FSR & FBC. He said he hasn't had any issues with the rifle before. No damage, No injury. df

Firearm Information

 Mfg.
 Type
 Model/Ga.
 SKU
 Serial
 Bbl.
 DOM

 Remington
 CF/BA
 700/204 RUGER
 26196
 S6558994
 AA
 3/20/2006 2:45:04 PM

 $\begin{array}{ccc} \textbf{Date} & \textbf{Where Purchased} & \textbf{Accessories} & \textbf{Original} \\ \textbf{Purchased} & \textbf{Owner} \end{array}$

3/2/2007 SIMMONS GUN SPECIALTIES
I

Y

CONCERN:FSR,FBC

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Reim. Cash Date APV APV

Per Ilion - Quote to repair @ a discount

Repair/Replacement Repair/Replacement
Cost Date

10/26/12: Mailing ARS & forms. df 11/29/12: Per Ilion - TA set screws altered. Trigger not returning properly. Replace TA, clean & test at 1/2 normal cost - quote. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		11/27/2012
Examination	Product Type		RF
	Action Type		A

PrintDisplay Page 2 of 2

<u> </u>	Assigned To		J.BALIO
Cause	4006	Altered Adjustments or Components	
	Description		22" 204 RUGER FL SS
	Date Code		AA
Barrel	Bore Plugged	False	
	Bulged	False]
	Fired	False	1
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning]
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning]
_	Notch Condition	Select]
-	Exterior Condition	Slightly Worn; Not Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	Select	.013
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	1 6818	False	
	Condition	Slightly Worn; Not Functioning	TRIG NOT RETURNING PROPERLY
Tricon	Pull	Select	2#
Trigger	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Non-Bolt Lock]

8091

October 26, 2012

Cory Fisher 2898 Grand Prairie Hwy Washington, LA 70589 Phone: 337-945-7392

Ref: #8091, Model 700, Serial # S6558994

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our facility for examination and service request.

Please include a copy of this <u>letter and service request</u> to put inside the shipping container. The letter and service request inside are important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results. I will contact you once I get the report.

Fax: 336-548-7883

I hope this action will keep you a loyal Remington customer.

Sincerely, Dell Fulcher Consumer Affairs Administrator Remington Arms Co., LLC Phone: 336-548-8686

DECLIVE 1 10V 2 9 20:2

\$6558994

RE00289893

J.A. Set Screws a Hered TRIQ. NOT PUTURNING PROPRETY. Pup hace TPA, CLAN + JEST At /2 NORWA 120ST.

Q

Remington Arms Company, LLC • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

Service Request

Remington Service PO Box 700

Madison, NC 27025-0700 ATTN: Product Service

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

·						
Service Request Number SR00033099	Serial Number / Description S6558994			Date of	Request:	10/26/2012 10/26/2012
	Model 700 RIFLE Caliber: 204					
Customer:	Widdel 700 Idi EE Canbel. 204	Dest	ination:			
CORY FISHER			Arms Services			
2898 GRAND PRAIRI	E HWY		14 Hoefler Ave			
	•			TIO		
WASHINGTON, LA 7	/0389 02		Ilion, NY 13357	US		
Email:			Email:		•	
Your request for service on the returned. If not, you will be co	e item(s) will be evaluated by our repairman ontacted with an estimate before work is per	to determine if it is covered u formed.	nder our warranty po	licy. If it is	s your firearm	will be repaired and
				9-27-3-2 7		
Reason For Return	PRODUCT SERVICE FOR INSPECTI	ON				
	NOD COL CENTION I CIN MINISTER I					
Service Request Section						
Product Service # 8091	The second secon				-	
Parts And Service Details		Control of the second section section of the second section sect	1 4 1000 65 65	. ४.५३३	na ere e essent am	PROSESSES PROPERTY OF A PART AND
Material Type	Description	Qty Needed	Warranty	<u>. — (r - µ</u>	Price	Disc Amount
		Needed	•			
	,			*		
			•			
					•	•
			•			
			•			•
	•					
						I
			•			
						•
	•		•		٠.	ı
THIS IS NOT AN INVOICE TO	his is a pra actimate to anni-	or realized the it/->		٠.	h Tokoli	20
being sent based on the convers	his is a pre-estimate to repair, recondition, o ation with our representative.	or replace the item(s)			b Total: Sales Tax:	.00
·				Gr	and Total:	\$.00

Print

Reset

Model Number: 700 L, V, S, F	Se Number: <u>5 6558</u>	rial 1994			
Are you the original ow	ner?: 12 YES □ N	0			
Name: CORY FISHER	Date of Purchase:				
Address (no 2898 GRAND PRAIRIE	PO Boxes):				
City: WASHINGTON	State: LA.	Zip: 70589			
Phone (Daytime): 337-826-5396	Fax:				
E-mail Address:(if e-mail address is provided be sent) <u>C かんした</u> Poison を	led, notification of received the second of	pt and shipment will			
E-mail A					
☑ I would like to receive future e					
RIFLE FIRES WHEN BOLTING WHEN SAFTEY IS ON FIRE. AND ALSO, IF SAFTEY IS ON ROUND IS CHAMBERED, WHEN FIRE POSITION, RIFLE FIRES WIT	N SAFE POSITION SAFTEY IS PUT HOUT PULLING T) AND A LIVE INTO THE			
500 characters left Ammunition Information:					
Manufacturer: HORN FOY		ER (4) -(a')			
Manufacturer: #ORNFDY Type: 204 CAL'BER (40 GRAIN) Other (i.e. bullet weight/type, shot size,					
powder): 405/AIN BULLET (V-MAY)					
Handload In	formation:	·			
Powder Used:	Powder Weight:				
Case/Hull Used:	Primer Used:				
Bullet Type/Shot Size:	Reloader Used:				
Firearms Care (Cleani	ng and Lubrication):				

http://www.remington.com/asp/factory_repair_form.asp

8/25/2011

Brand of cleaning solution us	ed: REM. DiL
How often do you c rounds)	lean the bore? (Months or Number of EVERY DROWNOS
How often do you cle	ean the action? (Months or Number of
	EVERY GMONTHS OR AS NEEDED
How often do you clean the rounds	ne trigger assembly? (Months or Number of
Brand of lubricant used:	REM. O.L
	ricate the bore? (Months or Number of EVERY LD ROUNDS.
How often do you lubr	icate the action? (Months or Number of
rounds) j	NERY 20 ROWDS OF AS NEEDED
How often do you lubricate	the trigger assembly? (Months or Number of
Have you reviewed the cleaning an in our owners	d maintenance recommendations on our web site or smanual? >☑ YES □ NO
When was the last time that your repairman/gunsmith	firearm was serviced by a Remington authorized ?) NEVER
Wh performed?)	at were the services
	rearm by either UPS or Parcel Post to:
PRODUCT SERVICE	RETURN ADDRESS:
ARMS SERVICES	2898 GRAND PRAIRIE HWY WASHINGTON, LA. 70589
14 HOEFLER AVE. ILION NY. 13357	HOME # 337-826-5396
ILL ON 109, 1200	HOME 11 257 WW GOLD
THE SAME BOX WITH THE FIREA YOU FEEL YOU MUST SEND SEPARATE PACKAGE AND IN	E OR SPENT SHELLS IN YOUR FIREARM OR IN RM. THIS IS A VIOLATION OF FEDERAL LAW. IF D SPENT SHELLS PLEASE SEND THEM IN A ICLUDE NAME, ADDRESS (WITH ZIP CODE), AND SERIAL NUMBER OF YOUR FIREARM.
:: Pack your firearm for safety and	Imber of your firearm before sending it. to prevent further damage in shipping and handling. Preferably,
:: Remove all accessories f	lote: Original boxes may not be returned.) rom your firearm to prevent loss or damage. the outside and inside the box. Shipments without a
	proper

http://www.remington.com/asp/factory_repair_form.asp

8/25/2011

ARS LABEL REQUEST FORM

DATE:	10/26/2012	Service Request #	SR00033099
QUANTITY:	1	WEIGHT PER PACKA	AGE: 10 LBS
REQUESTED BY:	fulcherdm	email address:	I WILL MAIL LABEL
Business:		Remington Service PO Box 700 Madison, NC 27025-0700 www.Remington.com	
		LABEL INFORMATION	
MAIL LABEL TO:		CORY FISHER 2898 GRAND PRAIRIE HWY WASHINGTON, LA 70589 US SR00033099	
		Email:	•
RETURN II	EM TO:	ILN Arms Services	
		SVC GNDCOM BL WT 10.0 LBS	D.O LBS #PK 1 L CURRENCY USD
		HC 0.00 CNS 0.00 FRT: SHIPMENT PUB RATE CHARGES: S\ DV 0.00 COD 0.00 DC 0.00 DGD 0.00 AH 0.00 PR 0.00 TOT PUB CHG 10.88 PUB+HAND	/C T/P USD RS 0.50 ROD 0.00

ATTN: Product Service





