

Remington Arms Co., Inc.
Product Service
Legal Case #:7358

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
256535	2/1/2012	2/2/2012	2/2/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Gander Mt		Gander Mt	1912 Skibo Rd	Fayetteville	NC	28314		W 910-487-4036

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD				
S	Fires sometimes when disengaging safety	Cause:4006	Altered Adjustments or Components	Unknown
C		Concern:1007	Fired on Safe Release	

2/16/12 Per note with rifle, fires sometimes when disengaging safety.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/2506 REM	n/a	A6285330	CI	4/6/1976
Date Purchased	Where Purchased	Accessories	Original Owner			
	SOUTHERN GUN DIST MIAMI FL	TWO PIECE BASE	U			

CONCERN: FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean, test fire at BLSM program price						
	Repair/Replacement Cost	Repair/Replacement Date				
	103.68	2/16/2012				

2/16/12 Per Ilion, trigger assm dirty and sticky. Set screws altered. Trigger not returning. Replace TPA, clean, test fire at BLSM program price.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		2/2/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4006	Altered Adjustments or Components	IMPROPER MAINTENENCE
Barrel	Description		24" 2506 REM
	Date Code		CI
	Bore Plugged	False	
	Bulged	False	
	Fired	False	

	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.007
	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	DIRTY, STICKY TRIG NOT RETURNING WILL FOLLOW DOWN
	Pull	---Select---	3.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	



7358

Service Request

Service Order # 5031

24"
CI 4/76
3.54
.007

SHIPPED TO VENDOR/STORE:

Remington Repair FFL# 6-16-01996
14 Hoefler Ave

Ilion, NY 13357

Attn:

Date Shipped: 01/24/2012 Phone: (800) 243-9700

RETURN SHIP TO:

Gander Mountain, FFL# 1-56-000-00-00-03488
Attn: Gun Parts Dept.
1912 Skibo Road
Fayetteville, NC 28314

FIREARM INFORMATION:

Manufacturer: Remington Arms Co Inc.
Model: 700

Type: Rifle
Cal/Ga.: .25-06cal

Serial Number: A6285330
Cased?: ☐

DESCRIPTION OF ITEM RETURNED:

REM.700 SER.# A6285330 BLUE WOOD BOLT RIFLE

REASON FOR RETURN:

TRIGGER PROBLEMS. FIRES SOMETIMES WHEN DISENGAGING SAFETY PLEASE REPAIR

ATTENTION VENDOR

Please contact me with any questions or concerns.

Walter Jackson/Randal Stroud
(910) 487-4036

BILLING INFORMATION:

Please include the service order number on all invoices and correspondence:

SHIP TO ABOVE ADDRESS

Forward all invoices to: **Gander Mountain**
Attn: Roy Christensen
6801 120th Ave
Kenosha, WI 53142

RECEIVED
FEB 09 2012

BY:

T.A. dirty + sticky, set screws
altered. Trig. not returning.
replace TPA, clean + test fire
under BLP Con # 20. + ship

Quote

Serial Number: **A6285330**

Model: **700**



DE00254525





