Remington Arms Co., Inc. Product Service Legal Case #:8395

Case Information

RE# Date Opened Date Opened(PS) **Date Closed** Incident Date Pre Lit Lit Obsolete 293754 12/20/2012 12/21/2012 12/21/2012

Customer Information

Business First Name Last Name Street City State Zip Age Contact 3500 Market Place Circle Ste B Reporter Gander Mt Gander Mt Traverse City MI 49684 H 231-929-5590

Incident Information

Claims Repair Est. Medical Treatment Medical Status Codes

ΡI

PD Cause: 4006 Altered Adjustments or Components S Fired when safety was released Concern: 1007 Fired on Safe Release

Unknown

1/8/13 Per note with rifle, gun fired when safety was taken off. Do safety recall and check trigger.cm

Firearm Information

DOM Mfg. Type Model/Ga. SKU Serial Bbl. Remington CF/BA 700/270 WIN n/a A6794839 OV 7/22/1979

Date Purchased Where Purchased Accessories Original Owner

PAMIDA OMAHA NE SCOPE BASE U

CONCERN: FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Cash Reim. Cash Settlement Release of Claims Release Date Reimbursement Settlement Date APV Date APV

Per Ilion, replace TPA, clean and test at BLSM program price

> Repair/Replacement Repair/Replacement

> > Cost Date

29.04 1/8/2013

1/8/13 Per Ilion, trigger assm dirty and set screws altered. Replace TPA, clean and test at BLSM program price.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date]	12/21/2012
	Product Type		RF
	Action Type	· ·	A
	Assigned To]	J.BALIO
Cause	4006	Altered Adjustments or Components	IMPROPER MAINTENENCE
Barrel	Description		22" 270 WIN
	Date Code]	OV
	Bore Plugged	False	
	Bulged	False]
	Fired	False	\mathbf{I}
	Fired while Obstructed]	
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	7

	Shroud	Slightly Worn; Functioning	Ħ
Bolt	Face	Slightly Worn; Functioning	=
	Handle	Slightly Worn; Functioning	
Extractor	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	=
	Cut Condition	Slightly Worn; Functioning	=
Locking	Ext/Eject Test	False	
	Block Condition	Select	
	Lug Condition	Slightly Worn; Functioning	=
Overall	Notch Condition	Select	=
	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	=
-	Fore End Condition	Select	=
	Condition	Slightly Worn; Functioning	-
Receiver	Bulged	False	7
	Description		BOLT LOCK SAFETY
Safety	Function	Like new; Functioning	
	Lift	Select	.012
	Notch	Slightly Worn; Functioning	
	T	Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Not Functioning	DIRTY,TRIG NOT RETURNING
Trigger	Pull	Select	3#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		SCOPE BASE



Service Request

Service Order # 7833

SHIPPED TO VENDOR/STORE:

Remington Repair FFL# 6-16-00726 14 Hoefler Ave

Ilion, NY 13357 -

Attn:

Model:

Date Shipped: 12/11/2012

Phone: (800) 243-9700

RETURN SHIP TO:

Gander Mountain, FFL# 4-38-055-01-7B-02234

Attn: Gun Parts Dept.

3500 Market Place Circle Ste B

Traverse City, MI 49684

FIREARM INFORMATION:

700

Manufacturer: Remington Arms Co Inc.

Rifle Type:

Serial Number: A6794839

Cal/Ga.: 270

Cased?:

DESCRIPTION OF ITEM RETURNED:

COMPLETE FIREARM

REASON FOR RETURN:

GUN FIRED WHEN SAFETY WAS TAKEN OFF DO SAFETY RECALL AND CHECK TRIGGER **THANKS**

ATTENTION VENDOR

Please contact me with any questions or concerns.

MICHAEL ROBINSON (231) 929-5590

BILLING INFORMATION:

Please include the service order number on all invoices and correspondence:

SHIP TO ABOVE ADDRESS

Forward all invoices to:

Gander Mountain (262-857-3757)

Attn:HOLLY FRENCH **6801 120TH STREET**

KENOSHA, WISCONSIN 53140

JAN 0 3 2013

T.A. dirry+set screws Alt.
Mr. 704, cleart rost und BCP
For 20+ Q

BA6794839









