

Remington Arms Co., Inc.
Product Service
Legal Case #:7929

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
281823	9/12/2012	9/13/2012	9/13/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Gilmer Pawnshop Inc		Gilmer Pawnshop	1105 US Hwy 271 North	Gilmer	TX	75644		W 903-843-3170 H 903-762-1911 C 903-790-7549
Incident		Eddy	Coleman	448 Old US Hwy 271 North	Gilmer	TX	75644		

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD				
S	Fires when you close the bolt	Cause:4015 Improper Maintenance Concern:1008 Fired on Bolt Closing	Unknown	
C				

9/21/12 Per letter with rifle, this weapon will fire when you bolt a shell into the chamber and close the bolt. It will prematurely fire at times.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPRG	n/a	6367641	DT	9/1/1970
Date Purchased	Where Purchased	Accessories	Original Owner			
	MONROE HD MONROE LA	TWO PIECE BASE	U			

CONCERN: FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Replace TPA, clean and test at BLSM program price						
	Repair/Replacement Cost	Repair/Replacement Date				
	29.44	9/21/2012				

9/21/12 Per Ilion, trigger assm is contaminated with a dried and sticky lube residue causing parts to bind and work sluggish. Replace TPA, clean and test at BLSM program price.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
------	----------	------	---------

http://cns03an13:200/nsaann/PrintDislay.aspx?ID=7929&Tvne=Case

9/21/2012

Examination	Examiner	B.TRAVIS	
	Exam Date	9/13/2012	
	Product Type	RF	
	Action Type	A	
	Assigned To	T.NAGLE	
Cause	4015	Improper Maintenance	
Barrel	Description	22" 3006 SPRG	
	Date Code	DT	
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Not Functioning	BINDS
	Extractor	Condition	Slightly Worn; Functioning
Cut Condition		Slightly Worn; Functioning	
Ext/Eject Test		False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description	BOLT LOCK SAFETY	
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	N/A
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	Tests	False	

Trigger	Condition	Slightly Worn; Not Functioning	SEAR AND TRIGG FROZEN TO SIDE PLATES WHEN RECEIVED
	Pull	---Select---	N/A
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

7929

22"
5/9/70

Eddy Coleman
448 Old U.S. Hwy 271 N.
Gilmer, Texas 75644

Enclosed you will find one stock and one barrel for Remington model 700 BDL 30:06
This weapon will fire when you bolt a shell into the chamber and close the bolt, it will
premature fire at times. I am sending this weapon back for proper retro-fit that will
eliminate this very dangerous problem. The serial number is as follows **6367641**. If you
need to contact me please call. Home phone is 903-762-1911, my cell is 903-790-7549. I
purchased this gun new in 1969 from Tony's Sporting Goods, Longview, Texas.
You will also find a business card for return shipment, which is:

Gilmer Pawnshop, Inc.
1105 U.S. Hwy 271 N.
Gilmer, Texas 75644

There Telephone number is 903-843-3170 If you need to contact them for questions on
shipping and firearms license.

Serial
Number:

6367641

Model: 700



RE00281823

RECEIVED
SEP 17 2012

BY: _____

T.A. is contaminated w/A dried
+ sticky lube residue causing parts
to bind + work sluggish. Replace
TPA, clean + rust under BCP Ron
\$20. +

Q



1105 U.S. Hwy. 271 N.
Gilmer, TX 75644
(903) 843-3170

Buy, Sell, Trade





