

Remington Arms Co., Inc.  
Product Service  
Legal Case #:8132

## Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
287200		11/8/2012	11/8/2012	11/5/2012			

## Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Daniel	Hamerlinck	137 North Harris Rd	Pearcy	AR	71964		

## Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD				
S	Fired when safety was released	Cause:4038 Could Not Duplicate Concern	Unknown	
C		Concern:1007 Fired on Safe Release		

11/8/12 Per note on repair, "SMP GUN FIRES WHEN TAKING OFF SAFE".cm

## Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl	DOM
Remington	CF/BA	700/270 WIN	n/a	379786		
Date Purchased	Where Purchased	Accessories	Original Owner			
	CENT BASE FUND APO SAN FRAN		U			

Ammunition Information - None Defined

Other Products Information - None Defined

## Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean and test at BLSM program price						
	Repair/Replacement Cost	Repair/Replacement Date				
	29.44	11/8/2012				

11/8/12 Per Ilion, could not duplicate concern. Replace TPA, clean and test at BLSM program price.cm

## Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		
	Exam Date		10/29/2012
	Product Type		RF
	Action Type		A
	Assigned To		B. TRAVIS
Cause	4038	Could Not Duplicate Concern	PHOTOS IN FOLDER

Barrel	Description		22" 270 WIN
	Date Code		BR
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Sear	Lift	---Select---	.006
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	---Select---	4#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

8132

frmRepairMain - FGI Repairs

File Add Repair Estimate Repair Expedite Repair Inquiry Repair Tools CSR Tools Reports Table Maintenance System

frmRepairInquiry - Repair Inquiry

Repair Number: RE00287200 Serial: 379786 Model 700 Center Fire Caliber: 270 Repairman: Bruce Travis  
 Verify Repair: WIN Status: Shipped 11/5/2012 10:00:04 PM

ADDRESS INFORMATION

Customer Received from Return To Received from

Name: DANIEL HAMERLINCK DANIEL HAMERLINCK  
 Address 1: 137 NORTH HARRIS RD 137 NORTH HARRIS RD  
 Address 2: PO Box: PO Box:  
 City: PEARCY PEARCY  
 State: AR Zip Code: 71964 Country: US AR Zip Code: 71964 Country: US

FFL: 01011900

Contact / Condition Problems Estimate History / Status Shipping / Billing

Problems Reported

Code	Desc
M122	FORWARD TO PRODUCT SE

Repair Notes

could not duplicate concern, replace trigger plate assm, clean and test fire under bolt lock program for \$20.00 + shipping

Repairman's Comments

Problems Found

Code	Desc
M123	FORWARD TO PRODUCT SE

CSR Comments

Repair Search Refresh Close

mittellcs - ILN/Prod frmRepairMain LT268-MAD2 Thursday, Nov 8 2012 3:24 PM

4:04 PM 11/8/2012











