

Remington Arms Co., Inc.  
Product Service  
Legal Case #:7374

## Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
257491	2/6/2012	2/7/2012	2/7/2012				

## Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Harden's Gunshop		Harden's Gunsho	607 E King St	Newton	AL	36352		W 334-790-7214 E gharden@sw.rr.com

## Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4029 Over pressured shell - not returned			Unknown
S	Fired on safety release Concern:1007 Fired on Safe Release			
C				

2/23/12 Per note with rifle, the rifle was returned to this gunshop for repair. The rifle fired upon release of safety. Bolt stuck, case removed from rifle. Case damaged and will be sent to us upon our request.cm

## Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/270 WIN	29709	S6497429	PY	6/23/2004 9:59:32 PM
Date Purchased	Where Purchased	Accessories	Original Owner			
	AMERICAN ROD & GUN		U			

## CONCERN:FSR

## Ammunition Information

Mfg.	Type	Cal/Ga.	SKU	UPC	DOM	Mfg. Code
Hornady	/					
Concern	Other	Factory	Reload			
0:		Y	N			

## Other Products Information - None Defined

## Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
As a goodwill gesture can offer to repair as needed at 1/2 normal cost						
Repair/Replacement Cost	Repair/Replacement Date					

2/23/12 Per Ilion, bolt damaged and would not function. Trigger assm set screws altered. As a goodwill gesture can offer to repair as needed at 1/2 normal cost.cm

## Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		2/7/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4029	Over pressured shell - not returned	UNABLE TO CHECK FUNCTION OF TPA, BOLT IS SWELLED AND WILL NOT FUNCTION IN RECEIVER
	Description		24" 270 WIN

Barrel	Date Code		PY
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Abused; Not Functioning	
	Face	Abused; Not Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Missing	
	Cut Condition	Abused; Not Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	ISS	
Sear	Lift	---Select---	.013
	Notch	Slightly Worn; Functioning	
	Test Fired	False	
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	MIN TRIG RETURN
	Pull	---Select---	N/A
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Non-Bolt Lock	

Print

Reset

7374

247  
P46/04  
1013

<b>Model</b> Number: 700		<b>Serial</b> Number: S6497429	
Are you the original owner?: <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO			
<b>Name:</b> Harden's Gunshop		<b>Date of Purchase:</b> 10-4-2005	
<b>Address (no PO Boxes):</b> 607 E. King Street			
<b>City:</b> Newton		<b>State:</b> AL	<b>Zip:</b> 36352
<b>Phone</b> (Daytime): 334-790-7214		<b>Fax:</b> 334-299-6652	
<b>E-mail Address:</b> (if e-mail address is provided, notification of receipt and shipment will be sent) gharden@sw.rr.com			
<b>E-mail Address:</b> <input type="checkbox"/> I would like to receive future e-mail updates from Remington.			
<b>Please describe your problem and date of occurrence:</b> Rifle returned to us for repair. Rifle fired upon release of safety. Bolt stuck. case removed from rifle. case damaged and will be sent to you upon request.			
<div style="display: flex; justify-content: space-between;"> <div> <p><i>Thank</i></p> <p><i>Please repair as much as possible</i></p> </div> <div> <p><i>Bolt damaged + would not function. T.A. set screws altered. AS A Good-will gesture can offer to repair AS needed at 1/2 normal cost.</i></p> <p><i>Quote</i></p> </div> </div>			
<b>Ammunition Information:</b>			
<b>Manufacturer:</b> Hornady		<b>Type:</b> unkn	
<b>Other (i.e. bullet weight/type, shot size, powder):</b>			

Serial Number:

S6497429

Model: 700



RE00257491

<b>Powder Weight:</b>
<b>Primer Used:</b>
<b>Reloader Used:</b>
<b>ing and Lubrication):</b>

FEB 09 2012





