

Remington Arms Co., Inc.  
Product Service  
Legal Case #:7851

## Case Information

| RE#    | Date Opened | Date Opened(PS) | Date Closed | Incident Date | Pre Lit | Lit | Obsolete |
|--------|-------------|-----------------|-------------|---------------|---------|-----|----------|
| 278737 | 8/16/2012   | 8/20/2012       | 8/20/2012   |               |         |     |          |

## Customer Information

| Type     | Business | First Name | Last Name | Street             | City    | State | Zip   | Age | Contact        |
|----------|----------|------------|-----------|--------------------|---------|-------|-------|-----|----------------|
| Incident |          | James      | Hauck     | 4913 Rock Creek Rd | Cochran | PA    | 16314 |     | H 814-425-3202 |

## Incident Information

| Claims | Codes                                                      | Repair Est. | Medical Treatment | Medical Status |
|--------|------------------------------------------------------------|-------------|-------------------|----------------|
| PI     |                                                            |             |                   |                |
| PD     | Cause:4006 Altered Adjustments or Components               |             | Unknown           |                |
| S      | Fires on safety release Concern:1007 Fired on Safe Release |             |                   |                |
| C      |                                                            |             |                   |                |

8/31/12 Per note with rifle, fires when you take it off safety.cm

## Firearm Information

| Mfg.           | Type                     | Model/Ga.   | SKU            | Serial   | Bbl. | DOM       |
|----------------|--------------------------|-------------|----------------|----------|------|-----------|
| Remington      | CF/BA                    | 700/270 WIN | n/a            | A6364241 | EI   | 10/1/1976 |
| Date Purchased | Where Purchased          | Accessories | Original Owner |          |      |           |
|                | CLEARFIELD CLEARFIELD PA |             | U              |          |      |           |

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

| Settlement                                                | Release of Claims       | Release Date            | Reimbursement | Cash Settlement | Reim. Date APV | Cash Date APV |
|-----------------------------------------------------------|-------------------------|-------------------------|---------------|-----------------|----------------|---------------|
| Per Ilion, replace TPA, clean and test fire at BLSM price |                         |                         |               |                 |                |               |
|                                                           | Repair/Replacement Cost | Repair/Replacement Date |               |                 |                |               |
|                                                           | 103.18                  | 8/31/2012               |               |                 |                |               |

8/31/12 Per Ilion, trigger assm set screws altered and trigger is note returning properly. Replace TPA, clean and test fire at BLSM price.cm

## Examination[Remington/CF/BA]

| Part        | Sub-Part               | Code                              | Comment     |
|-------------|------------------------|-----------------------------------|-------------|
| Examination | Examiner               |                                   | B.TRAVIS    |
|             | Exam Date              |                                   | 8/20/2012   |
|             | Product Type           |                                   | RF          |
|             | Action Type            |                                   | A           |
|             | Assigned To            |                                   | T.NAGLE     |
| Cause       | 4006                   | Altered Adjustments or Components |             |
| Barrel      | Description            |                                   | 22" 270 WIN |
|             | Date Code              |                                   | EI          |
|             | Bore Plugged           | False                             |             |
|             | Bulged                 | False                             |             |
|             | Fired                  | False                             |             |
|             | Fired while Obstructed |                                   |             |
|             | Muzzle/Crown Condition | Slightly Worn; Functioning        |             |
|             | Firing Pin             | Slightly Worn; Functioning        |             |

|              |                    |                                |                                     |
|--------------|--------------------|--------------------------------|-------------------------------------|
| Bolt         | Shroud             | Slightly Worn; Functioning     |                                     |
|              | Face               | Slightly Worn; Functioning     |                                     |
|              | Handle             | Slightly Worn; Functioning     |                                     |
|              | Stop               | Slightly Worn; Functioning     |                                     |
| Extractor    | Condition          | Slightly Worn; Functioning     |                                     |
|              | Cut Condition      | Slightly Worn; Functioning     |                                     |
|              | Ext/Eject Test     | False                          |                                     |
| Locking      | Block Condition    | ---Select---                   |                                     |
|              | Lug Condition      | Slightly Worn; Functioning     |                                     |
|              | Notch Condition    | ---Select---                   |                                     |
| Overall      | Exterior Condition | Slightly Worn; Not Functioning |                                     |
|              | Stock Condition    | Slightly Worn; Functioning     |                                     |
|              | Fore End Condition | ---Select---                   |                                     |
| Receiver     | Condition          | Slightly Worn; Functioning     |                                     |
|              | Bulged             | False                          |                                     |
| Safety       | Description        |                                | M/700 BOLT LOCK SAFETY              |
|              | Function           | Like new; Functioning          |                                     |
|              | Sub-Assembly       | Non-ISS                        |                                     |
| Sear         | Lift               | ---Select---                   | .009                                |
|              | Notch              | Slightly Worn; Functioning     |                                     |
|              | Tests              | Test Fired                     | False                               |
| Feeding Test |                    | False                          |                                     |
| Trigger      | Condition          | Slightly Worn; Not Functioning | TRIG NOT RETURNING WILL FOLLOW DOWN |
|              | Pull               | ---Select---                   | 3.5#                                |
|              | Altered            | True                           | SET SCREWS ALTERED                  |
|              | Sub-Assembly       | M/700 Bolt Lock                |                                     |

James Hauck  
4913 Rock Creek Rd. 7851

Cochran, Pa. 16314

Serial # A6364241

Model 700 Remington BDL.

Phone (814) 425-3202

Fire's when you take it off  
of safety.

Serial  
Number:

A6364241

Model: 700



RE00278737

ote...

RECEIVED  
AUG 22 2012

BY:.....

T.A. set screws altered & Trig is NOT  
returning properly. replace TPA, count  
test fire under BCP Con # 20. + ship

Quote

72"  
3.5"  
.009  
EI 11/76





