## Remington Arms Co., Inc. Product Service Legal Case #:8377

Case Information

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete

293346 12/17/2012 12/18/2012 12/18/2012

Customer Information

City Type Business First Name Last Name Street State Zip Age Contact 57050 707th Rd. Incident Charles Hill Endicott NE 68350 H 402-729-2982

Incident Information

Claims Codes Repair Est. Medical Treatment **Medical Status** 

ΡI

PD Cause:4038 Could Not Duplicate Concern

Unknown

C

S FSR

SR# 35734 - Service Request Section: Gun fired when safety taken off. df

Concern:1007 Fired on Safe Release

Firearm Information

Mfg. Remington

Type CF/BA

Model/Ga. 700/270 WIN

SKU 25771 Serial Bbl. DOM

E6329304 EQ 10/21/1996

**Date Purchased** 

Where Purchased

Accessories

Original Owner

WAL-MART WAREHOUSE #3R

U

CONCEN: FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Settlement

Release of Claims

Release Date

Reimbursement

Cash Settlement Reim. Cash Date

APV

Date APV

Per Ilion - Quote to repair @ 1/2 normal cost

Repair/Replacement Repair/Replacement

Cost Date

12/20/12: Per Ilion - Could not duplicate concern. TA dirty. Can offer to replace TA, clean & test at 1/2 normal cost - quote. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		12/18/2012
	Product Type		RF
	Action Type		A
	Assigned To		J.BALIO
Cause	4038	Could Not Duplicate Concern	
	Description		22" 270 WIN

	Date Code		EQ
Barrel	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	SLUGGISH
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD SAFETY
	Function	Like new; Functioning	,
Sear	Lift	Select	.013
	Notch	Slightly Worn; Functioning	
	Tasta	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY
	Pull	Select	4.5#
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	

## Service Request

## Remington Service PO Box 700



Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

013

Service Request Number

Serial Number / Description

SR00035734

Email:

E6329304

Model 700 RIFLE Caliber: 270

11/20/2012 Date of Request: 11/20/2012 Date Printed:

Customer: CHARLES HILL 57050 707TH ROAD

Destination: Arms Services 14 Hoefler Ave Ilion, NY 13357 US

ENDICOTT, NE 68350 US

Email:

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return

M127 - TRIGGER PULL IS OUT OF FACTORY SPECS

M310 - PERFORM SAFETY CHECKS ON TRIGGER ASSEMBLY

Service Reguest Section

gun fired when safety taken off

Parts And Service Details Material Type

Description

Qty Needed

Warranty

Price

Disc Amount

could not dup, concern T.A. dirty. CHNOFfen to My. TAA clear+ 1-st of 1/2 change

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) being sent based on the conversation with our representative.

BY: ..... Sub Total:

.00 .00

Est Sales Tax:

\$.00











