

Remington Arms Co., Inc.
Product Service
Legal Case #:7244

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
253154	1/9/2012	1/10/2012	1/10/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter		Peter	Holzapel	49 Apple Wood Ln.	Newfoundland	PA	18445		H 570-676-9953

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4006 Altered Adjustments or Components		Unknown	
S	Concern:1008 Fired on Bolt Closing			
C FBC				

SR# 7335 - Customer stated that he has had gun a long time, he has had a FBC with it, he took it to a gunsmith & the gunsmith cleaned, lubed & adjusted the trigger. He said the trigger is very sensitive. He feels it may need a redesigned trigger. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPRG	n/a	6799305	EY	10/1/1974
Date Purchased	Where Purchased	Accessories	Original Owner			
			Y			

CONCERN:FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Quote to repair under BLM						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$29					

1/16/12: Per Ilion - Could not duplicate concern. TA set screws altered, trigger not returning properly. Replace TA, clean & test fire under BLM - quote. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/10/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4006	Altered Adjustments or Components	
Barrel	Description		22" 3006 SORG
	Date Code		EY
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	SOME RUSTING ON BBL
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.008
	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Functioning	TRIG NOT RETURNING PROPERLY
	Pull	---Select---	2.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	

1. **Author(s):** [Name of the author(s)]
 2. **Title:** [Title of the document]
 3. **Subject:** [Subject of the document]
 4. **Keywords:** [Keywords related to the document]
 5. **Abstract:** [Abstract of the document]
 6. **Introduction:** [Introduction of the document]
 7. **Methodology:** [Methodology of the document]
 8. **Results:** [Results of the document]
 9. **Conclusion:** [Conclusion of the document]
 10. **References:** [References of the document]

Parts and Repairs: P:800-243-9700 F:336-548-7801 www.Remington.com

2211
EY10/70
2.5H
.008

PS 28047



Mr. Peter Holzapfel
49 Applewood Ln.
Newfoundland, PA 18445

1/2/2011

To whom it may concern,

As per our phone conversation, I am returning my Remington model 700 Serial #6799305 for inspection and or repair. As far as I can remember this gun was purchased at Edelman's sporting goods on Long Island N.Y. The rifle was purchased in 1979 or 1980 by my brother William Holzapfel as a Christmas gift. The problem I have been having for many years is that when unloading the gun, as a new round is loaded in the chamber, it fires without the trigger from time to time. A local gunsmith has looked at it and cleaned, lubricated, and adjusted the trigger assembly to try to help rectify the problem. The problem has gotten better, but on occasion it still happens. Also the release for the bolt mechanism may stick. The trigger is also very sensitive, but better than it used to be. It now has some travel when before it didn't. Because I hunt with my son, even though I practice safe firearm handling, I am concerned. If the triggers on this model were improved with a redesigned one, maybe that's what it needs. I like this rifle, as was in my family for many years. I appreciate your time in evaluation of this situation.

Thank you, Sincerely Peter Holzapfel.





