

Remington Arms Co., Inc.
Product Service
Legal Case #:7245

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
253134	1/9/2012	1/10/2012	1/10/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City State	Zip	Age	Contact
Reporter	Howell's Gun & Archery Ctr		Howell's Gun &	PO Box 501, Rt 202	Gray ME	04039		W 207-657-2324

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4006 Altered Adjustments or Components		Unknown	
S	Fired on bolt closing Concern:1008 Fired on Bolt Closing			
C				

1/26/12 Per note with rifle, this gun has misfired 3 times and goes off when closing the bolt.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/22-250 REM	n/a	A6252756	BI	1/14/1976
Date Purchased	Where Purchased	Accessories	Original Owner			
	MATHEWS & BOUCHER ROCHESTER NY	TWO PIECE BASE	U			

CONCERN: FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean, test fire at BLSM program price						
Repair/Replacement Cost	Repair/Replacement Date					
30.40	1/26/2012					

1/26/12 Per Ilion, trigger assm very dirty and set screws altered. Trigger no returning under sear properly. Replace TPA, clean, test fire at BLSM program price.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/10/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4006	Altered Adjustments or Components	IMPROPER MAINTENENCE
Barrel	Description		24" 22-250 REM
	Date Code		BI
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.009
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	VERY DIRTY, TRIG NOT RETURNING PROPERLY WILL FOLLOW DOWN
	Pull	---Select---	2.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE



HOWELL'S GUN & ARCHERY CENTER

P.O. BOX 501 - ROUTE 202
GRAY, MAINE 04039
(207) 657-2324
www.howellsguns.com

7245

24"
BI 1/76
2.5#
.009

CUSTOMER'S ORDER NO.		PHONE		DATE	
				12-29-11	
NAME					
ADDRESS					
Remington Arms Repair Dept					
SOLD BY	CASH	C.O.D.	CHARGE	ON ACCT.	MDSE. RET'D.
QTY.	DESCRIPTION			PRICE	AMOUNT
	THIS GUN HAS MISS FIRED 3 TIME AND GOES OFF WHEN CLOSING BOLT				
SENT TO REMINGTON NEW TRIGGER FROM Remington					
miss fired 3 times Don't trust					
				TAX	
				TOTAL	

RECEIVED
JAN 16 2012

BY:

red by this bill.

Thank You

27389

T.A. very dirty + set screws altered.
TRIG. NOT RETURNING UNDER SEAR properly.
Repha TPA, clean + Test fine under
BSP for 20. + ship

Quote

A6252756

Model: 700



RE00253134







