

Remington Arms Co., Inc.
Product Service
Legal Case #:8130

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
288471	11/7/2012	11/8/2012	11/8/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Jim's Firearms	---	Jim's Firearms	5760 Siegen Ln, Ste A	Baton Rouge	LA	70809		W 225-293-5467 F 225-293-1490

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4006	Altered Adjustments or Components		
S FSR	Concern:1007	Fired on Safe Release	Unknown	
C				

Dealer sent rifle in & stated gun fires when safety is disengaged. Consumer would like trigger modification program. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial Bbl.	DOM
Remington	CF/BA	700/3006 SPRG	n/a	6631961	CX 4/1/1973
Date Purchased	Where Purchased	Accessories	Original Owner		
	STRATTON&BALDWIN NEW ORLNS LA	SCOPE BASE,MUZZLE BREAK,AFT MKT DM SYSTEM	U		

CONCERN: FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Quote to repair under BLM						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$29					

11/13/12: Per Ilion - TA dirty & set screws altered. Replace TA, clean & test under BLM - quote. Customer apprvd quote & paid on 11/9/12. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		11/8/2012
	Product Type		RF
	Action Type		A
	Assigned To		J.BALJO
Cause	4006	Altered Adjustments or Components	
Barrel	Description		22" 3006 SPRG
	Date Code		CX
	Bore Plugged	False	
	Bulged	False	

	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	SLUGGISH
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Magazine	Condition	---Select---	
	Box Condition	Missing	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.005
	Notch	Slightly Worn; Functioning	
Feeding Test	Tests	Test Fired	False
		False	
Trigger	Condition	Slightly Worn; Not Functioning	DIRTY WILL FOLLOW DOWN
	Pull	---Select---	9.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		SCOPE BASE,MUZZLE BREAK,AFT MKT DM SYSTEM

JIM'S FIREARMS, INC.
5760 SIEGEN LANE, SUITE A
BATON ROUGE, LOUISIANA 70809
(225) 293-5467 Fax (225) 293-1490

8/30

DATE

10-25-12

2271

ATTENTION OF:

Shop

CX4/73

SUBJECT

Rem 700 30-06

9.5#

SN: 6631961

.005

TO: Remington Arms Co., Inc
40 Arms Service Division
14 Hoefler Avenue
Illon, NY, 13357

Firearm fires when safety is disengaged, Customer
Would like to include firearm in trigger modification
program. Thank you

Serial
Number:

6631961

Model: 700



RE00288471

IED

FSR

T.A. dirty + set screws altered.
Replace TPA, clean + test under
BLP Run & test Q

RECEIVED
NOV 13 2012

BY:.....





