Remington Arms Co., Inc. Product Service Legal Case #:7778

Case Information

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete 274347 7/13/2012 7/16/2012 7/16/2012

Customer Information

First Type Business Last Name Street City State Zip Age Contact Name

W 724-423-1100 Johnson's Gun Johnson's 2231 Mt. Pleasant Rd Norvelt PA 15674 E Box 175

guns@zoominternet.net

Incident Information

Depot

Claims Codes Repair Est. Medical Treatment Medical Status

PΙ

PD Cause:4015 Improper Maintenance Unknown

S Fired when safety was released Concern: 1007 Fired on Safe Release

Gun D

7/23/12 Per note with rifle, when gun was loaded and the safety was released, the gun went off before the trigger was pulled.cm

Firearm Information

Mfg. Type Model/Ga. SKU Serial Bbl. DOM Remington CF/BA 700/270 WIN 20000 6804902 RY 11/1/1974

Date Purchased Where Purchased Accessories Original Owner

SCOPE BASE, BOTTOM HALF RINGS U

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Reim. Cash Cash Settlement Release of Claims Release Date Date Date Reimbursement Settlement APV APV

Per Ilion, replace TPA, clean, test at BLSM price

> Repair/Replacement Repair/Replacement Date

Cost

61.94 7/23/2012

7/23/12 Per Ilion, trigger assm dirty and sticky, parts work sluggish. Replace TPA, clean, test at BLSM price.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment	
Examination	Examiner		B.TRAVIS	
	Exam Date		7/16/2012	
	Product Type		RF	
	Action Type		A	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=7778&Type=Case

7/23/2012

	Assigned To		T.NAGLE
Cause	4015	Improper Maintenance	
	Description	]	22" 270 WIN
	Date Code		RY
	Bore Plugged	False	
_	Bulged	False	] .
Barrel	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Select	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
W. 1922	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking .	Block Condition	Select	]
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	]
Sear	Lift	Select	.005
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	16565	False	
Trigger	Condition	Slightly Worn; Not Functioning	DIRTY STICKY PARTS WROK SLUGGISH. WILL FOLLOW DOWN
	Puli	Select	4.5#

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=7778&Type=Case

7/23/2012

	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		SCOPE BASE,BOTTOM HALF RINGS

7/23/2012

## JOHNSON'S GUN DEPOT

271/71

2231 Mt. Pleasant Road - Box 175 Norvelt, PA 15674

Phone: 724.423.1100 Fax: 724.423.1454

email: guns@zoominternet.net ---- www.johnsongundepot.com

Date: 7/6/12	RMA # (If needed)				
TO: REMINISTON ARMS	SERVICES				
Address: 14 HOEFLER AVE	· · · · · · · · · · · · · · · · · · ·				
City: 1 1 1 0 N State:	11 zip: 13357				
Attention: REPAIR					
Dear Sir or Madam:					
We are sending the following firearm to you:					
Make: REMMINGTON Model: 700 Serial: B6225176 Caliber/Ga: 270					
for:					
The following is a description of the problems with this firearm or the work that is needed to this firearm:					
when gun was loaded and the					
Safety was released the Sur went off, defore tuggine was pulled EGEIVE					
off, defore luggen	was Spulled ECERVET JUL 1 9 2012				
6804902	T. A. Ljorty + Sticky PARTS WORK				
Model: 700	Sluggish. Riplace TPA, cleare				
	Test under BLP Con & 20, + ship.				
RE00274347	Quote				
tact us concerning this fireram, please direct your ca	A CONTRACTOR OF THE CONTRACTOR				
	Representative of Johnsons Gun Depot				





