

Remington Arms Co., Inc.
Product Service
Legal Case #:7407

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
258671	2/15/2012	2/16/2012	2/16/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Juniata Trading Co		Juniata Trading	13921 Lincoln Hwy	Everett	PA	15537		W 814-652-5878

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4015	Improper Maintenance		
S	Fired on bolt closing	Concern:1008 Fired on Bolt Closing	Unknown	
C				

3/1/12 Per note with rifle, will fire sometimes when bolt is closed.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/270 WIN	n/a	316189	RP	11/1/1967
Date Purchased	Where Purchased	Accessories	Original Owner			
			U			

CONCERN:FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean, test at BLSM program price						
	Repair/Replacement Cost	Repair/Replacement Date				
	30.40	3/1/2012				

3/1/12 Per Ilion, trigger assm dirty and sticky, parts work sluggish and bind. Replace TPA, clean, test at BLSM program price.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		2/16/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4015	Improper Maintenance	
Barrel	Description		22" 270 WIN
	Date Code		RP
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	

Bolt	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.005
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	DIRTY,STICKY.SEAR BINDING WILL FOLLOW DOWN
	Pull	---Select---	5.5#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	



7407
Junjata Trading Co., Inc.

22"
RP11/67
S.S.
2005
13921 Lincoln Highway
Everett, PA 15537
Phone: (814) 652-5878
Fax: (814) 652-2163

2-9-12

PLEASE Find Remington 700 270win
#316189 which will FIRE sometimes
when bolt is closed PLEASE REPAIR
& RETURN.

THANK YOU
JERRY

Serial
Number:

316189

Model: 700



RE00258671

RECEIVED
FEB 20 2012

BY:

T.A. dirty & sticky parts work
sluggish BIND. replace TPA,
clean test under BCP for
8 W.O.T

Quote

GIFT SHOP - SPORTING GOODS - BUY - SELL - TRADE

PS 28206





