

Remington Arms Co., Inc.
Product Service
Legal Case #:8058

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
285885	10/17/2012	10/18/2012	10/18/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Seaun	Levi	303 Cedar Ln	West Fargo	ND	58078		E sjlsnipe1@cableone.net

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD				
S	Fired when bolt was closed	Cause:4038 Could Not Duplicate Concern		Unknown
C		Concern:1008 Fired on Bolt Closing		

11/5/12 Per note on SR, gun went off when bolt was closed.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/338 LAPUA	84463	S6782773	AG	3/30/2012 1:41:31 PM
Date Purchased	Where Purchased	Accessories	Original Owner			
	BILL HICKS & CO LTD		U			

CONCERN: FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement - None Defined

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		10/18/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		26" 338 LAPUA
	Date Code		AG
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Like new; Functioning	
	Firing Pin	Like new; Functioning	
	Shroud	Like new; Functioning	

Bolt	Face	Like new; Functioning	
	Handle	Like new; Functioning	
	Stop	Like new; Functioning	
Extractor	Condition	Like new; Functioning	
	Cut Condition	Like new; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Magazine	Condition	---Select---	
	Box Condition	Like new; Functioning	
Overall	Exterior Condition	Like new; Functioning	
	Stock Condition	Like new; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Like new; Functioning	
	Bulged	False	
Safety	Description		STANDARD SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.013
	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Like new; Functioning	
	Pull	---Select---	4#
	Altered	False	40X TPA
	Sub-Assembly	M/700 Non-Bolt Lock	

PO Box 700
Madison, NC 27025-0700

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. **ENCLOSE THIS DOCUMENT WITH YOUR RETURN.**

26'
AG 3/12
4A
10/13

Service Request Number: SR00030585
Serial Number / Description: S6782773
Model 700 RIFLE Caliber: 338

8058

Date of Request: 10/02/2012
Date Printed: 10/02/2012

Customer:
SEAUN LEVI
303 CEDAR LN.
WEST FARGO, ND 58078 US

Destination:
Arms Services
14 Hoefler Ave
Ilion, NY 13357 US

Email: SJLSNIPE1@CABLEONE.NET

Email:

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return
M295 - EVALUATE AND REPAIR

Service Request Section
GUN WENT OFF, WHEN BOLT WAS CLOSED.

Parts And Service Details

Qty Needed	Warranty	Price	Disc	Amount
---------------	----------	-------	------	--------

Serial Number:
S6782773
Model: 700



RE00285885

RECEIVED
OCT 25 2012

BY:.....

could not duplicate concern
to restore confidence in rifle
will replace TPA, checkover & test
at N/C

WARRANTY

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the

Sub Total:	.00
Est Sales Tax:	.00
Grand Total:	\$.00





